



Enhancing our communities



# Bridge Inspections

**TOWN OF PARRY SOUND**

Inspection Summary Report

# Document Control

File:

220555

Date:


January  
12, 2023

Prepared by:

**Tatham Engineering Limited**  
8 Barron Drive  
Bracebridge, Ontario P1L 0A1  
**T** 705-645-7756  
tathameng.com

Prepared for:

**The Town of Parry Sound**  
52 Seguin Street  
Parry Sound, Ontario P2A 1B4

<b>Authored by:</b>	
	
Brian Wood, P.Eng. Manager - Bridges	

<b>Disclaimer</b>	<b>Copyright</b>
The information contained in this document is solely for the use of the Client identified on the cover sheet for the purpose for which it has been prepared and Tatham Engineering Limited undertakes no duty to or accepts any responsibility to any third party who may rely upon this document.	This document may not be used for any purpose other than that provided in the contract between the Owner/Client and the Engineer nor may any section or element of this document be removed, reproduced, electronically stored or transmitted in any form without the express written consent of Tatham Engineering Limited.

Issue	Date	Description
1	January 12, 2023	Inspection Summary Report

# Table Contents

**1 Introduction ..... 1**

**2 Inspection Summaries .....3**

2.1 Seguin Street Bridge .....3

2.2 Seguin River Pedestrian Bridge.....4

2.3 Cascade Street Bridge No.1 .....5

2.4 Cascade Street Bridge No.2 .....5

2.5 Waubuno Street Bridge.....6

**3 Recommendations .....7**

**Tables**

Table 1: Bridge Locations ..... 1

Table 2: Rehabilitation Costs ..... 7

**Appendices**

- Appendix A: Definitions
- Appendix B: OSIM Forms



# 1 Introduction

Tatham Engineering Ltd. was retained by the Town of Parry Sound to perform Detailed Visual Inspections (DVI) for 5 bridges at various locations within town limits. This work is required in compliance with Ontario Regulation (O.Reg.) 104/97 as amended by O.Reg. 472/10. This regulation states that bridges are to be inspected every two years and these inspections are to be conducted in general accordance with the Ontario Structure Inspection Manual (OSIM). The objectives of this work are to:

- Identify maintenance, repair, rehabilitation needs and load limit posting recommendations to protect and prolong the useful life of the structures; and
- Provide a basis for a management system for the planning and funding of the recommended works.

The bridges that were inspected are listed in Table 1.

**Table 1: Bridge Locations**

BRIDGE NAME	ROAD NAME	LOCATION
Seguin Street Bridge	Seguin Street	0.08 km West of River Street
Seguin River Pedestrian Bridge	Fitness Trail	0.10 km South of Seguin Street over Seguin River
Cascade Street Bridge No.1	Cascade Street	0.10 km East of Water Street
Cascade Street Bridge No.2	Cascade Street	0.02 km East of Water Street
Waubuno Street Pedestrian Bridge	Fitness Trail	Waubuno Street at Georgian Bay

The DVI's involve an element-by-element inspection of the structure. Elements are reviewed and their condition and performance are assessed based on observations made by the inspector. The inspection and terminology are in general accordance with the Ontario Ministry of Transportation (MTO) OSIM guidelines, available online under "MTO Technical Documents" at: <https://www.library.mto.gov.on.ca/SydneyPLUS/TechPubs/Portal/tp/TechnicalPublications.aspx>

In order to convey the results of the visual inspections, certain terms are used to identify particular deficiencies with respect to material condition and defects. Definitions of these terms can be found in the OSIM. Material defects and severity are classified and quantified, then the severity is translated to a condition state of Excellent, Good, Fair, or Poor. For example, a defect could consist of concrete scaling with a severity of Light, Medium, Severe or Very Severe. These severities are then translated to the OSIM defined condition states. Material Defects can be found in the OSIM Part 1 Section 1.2 Material Defects. Part 1 also provides material defects for various elements and associated materials. Part 2 Section 2.4 Material Condition States, 2.5 Suspected



Performance Deficiencies, and Section 2.9 Appendix A – Combined Summary of Material Defects and Condition States provide guidelines for determining the appropriate condition state of Excellent, Good, Fair, or Poor.

Maintenance needs, rehabilitation, or replacement recommendations are then determined with associated time frames to assist the Town with prioritization of the work.

This report summarizes the results of the detailed visual inspections and provides costing and scheduling information for the recommended works. A brief listing of terms used to identify deficiencies with respect to condition or performance states are provided in Appendix A.



## 2 Inspection Summaries

The following summarizes the inspection observations and recommendations. In addition to the deficiencies addressed by the recommended works, a complete compilation of condition and performance information for each bridge can be found in the OSIM reports which include photos of each element. These reports are included in Appendix B.

Recommended works are categorized into maintenance or rehabilitation work. These categorizations are intended to differentiate between smaller scale maintenance work that could be completed by the Town's works department, and larger scale rehabilitation work that may require engineering design and tendering of the construction works. Additional Investigations such as Material Condition Surveys, Underwater investigations, Structure Evaluations, etc. are identified both in the summaries below and the OSIM reports, along with recommendations for Enhanced OSIM Inspections which typically consist of the use of a Bridgemaster or similar bucket truck to enable a close-up within arms reach of all areas of the structure.

### 2.1 SEGUIN STREET BRIDGE

The 55.0 m single span structure consists of a concrete deck on three trapezoidal weathering steel box girders supported on concrete abutments. The east abutment is founded on steel H-piles driven to bedrock, and the west abutment is founded on concrete footings on bedrock. The bridge is 20.6 m wide out-to-out with a clear roadway width of 15.0 m.

The bridge is in generally good condition. The sidewalks are exhibiting spalling and delaminations. The interior girder ends are corroding, with debris and moisture contributing to the deterioration. It is proposed the next OSIM inspection occur in 2024.

The following Additional Investigation is recommended:

- A Bridge Master inspection of the exterior of the girders (2 Years).

The following maintenance is recommended:

- Replace northeast approach barrier connection with standard connection (2 Years).
- Annual bridge cleaning, particularly the deck joints (1 Year).

The following rehabilitation is recommended:

- Sidewalk Concrete Repair: Includes spalls and delaminations (1-5 Years).
- Interior Girder Ends: Clean and recoat steel inside boxes to mitigate continued corrosion (1-5 Years).



## 2.2 SEGUIN RIVER PEDESTRIAN BRIDGE

The Seguin River Pedestrian Bridge is located on a fitness trail that was converted from a former railway bed, essentially rails to trails. It is approximately 0.1 km south of the Seguin Street Bridge and crosses the Seguin River. The 96.5 m 12-span structure consists of nine eastern timber trestles, followed by a steel through-plate girder span, a deck on steel girder span, and another steel through-plate girder span.

The bridge is in generally good to fair condition with localized areas in poor condition. Barrier height should be increased to 1.37 m to meet CHBDC requirements for cyclists, however 1.2 m may be used based on owner approval. It is proposed that the next OSIM inspection occur in 2024.

The following Additional Investigation is recommended:

- An Underwater Investigation of the piers to confirm condition (2 Years).
- During a 2012 inspection, low water levels revealed timber cribbing supporting the concrete piers. Based on visual observations from boat access, deterioration of the timber was evident and due to condition and age an Underwater Investigation is recommended with a Priority of Normal, i.e., usually within 2 years.

The following maintenance is recommended:

- Clean off debris from west abutment bearing seats (1 Year).
- Ongoing timber member replacements (1 Year).

The following rehabilitation is recommended:

- Span 12 steel repairs (6-10 Years).
- West abutment concrete repair (6-10 Years).
- Three concrete piers concrete repair (6-10 Years).



### 2.3 CASCADE STREET BRIDGE NO.1

The two span 26.5 m structure consists of precast concrete box girders supported on concrete abutments and pier. The bridge is 11.2 m wide out to out with a clear roadway width of 8.5 m.

The bridge is in generally good condition. There is concrete deterioration along the top and front curb face of the sidewalk, and along the east and west exterior soffits. There are spalls and delaminations of girder soffit concrete at the girder ends. The asphalt is beginning to exhibit deterioration including rutting and cracks. No Additional Investigations are recommended at this time. It is proposed the next OSIM inspection occur in 2024.

The following maintenance is recommended:

- Repair punctured railing (2 Year).
- Replace damaged guide rail sections, rotten wood post, install end treatments (2 Year).
- Annual bridge cleaning (1 Year).

The following rehabilitation is recommended:

- Sidewalk top surface and face of curb concrete repair (1-5 Years).
- East and West exterior soffit concrete repair (1-5 Years).
- Girder soffit ends concrete repair (1-5 Years).
- Replace asphalt wearing surface, apply waterproofing membrane (1-5 Years).

### 2.4 CASCADE STREET BRIDGE NO.2

The 10.0 m span is a concrete rigid frame structure with vertical legs. The bridge is 11.2 m wide out to out and has a clear roadway width of 8.0 m.

The bridge is in excellent to good condition. The asphalt is beginning to exhibit deterioration including rutting and cracks. No Additional Investigations are recommended at this time. There is no rehabilitation recommended. It is proposed the next OSIM inspection occur in 2024.

The following maintenance is recommended:

- Upgrade barrier connections to structure at north quadrants (2 Years).
- Replace missing end caps on structure barrier (2 Years).
- Repair concrete void in south abutment wall (2 Years).
- Repair void at bottom of retaining wall (2 Years).
- Repair north approach asphalt (2 Years).
- Annual bridge cleaning (1 Year).





## 2.5 WAUBUNO STREET BRIDGE

The Waubuno Street Bridge is located along the Parry Sound Fitness trail and crosses Waubuno Street at Georgian Bay. It is a timber girder bridge with timber plank deck, timber barriers, and timber trestle supports. The structure has 3 spans of 3.73 m, 4.18 m, and 3.53 m each. The travelled width is 3.2 m, and the overall width is 3.6 m out to out. It is currently used by pedestrian and snowmobiles.

The bridge is in generally good to fair condition; However, there are a number of elements exhibiting deterioration and rot. No Additional Investigations are recommended at this time. It is proposed the next OSIM inspection occur in 2024.

The following maintenance is recommended:

- Fasten loose deck planks (1 Year).
- Relocate No Motorized Vehicles signs to be more visible (1 Year).

The following rehabilitation is recommended:

- Replace deteriorated deck planks (1-5 Years).
- Replace deteriorated curbs (1-5 Years).
- Replace deteriorated stringers (1-5 Years).
- Replace south abutment ballast wall (1-5 Years).
- Replace north abutment deteriorated sills (1-5 Years).
- Replace deteriorated pier columns (1-5 Years).



### 3 Recommendations

Overall, these five structures are in generally good to fair condition. The following is a brief summary of key recommendations.

**Seguin Street Bridge:** Sidewalk concrete repairs, steel girder interior ends rehabilitation. Bridge Master inspection of the exterior of the girders estimated at \$20,000.

**Seguin River Pedestrian Bridge:** Span 12 steel repairs, all pier concrete repairs, west abutment concrete repair. Underwater Investigation of the piers estimated at \$20,000.

**Cascade Street Bridge No. 1:** Sidewalk and exterior deck soffit concrete repairs, asphalt replacement.

**Cascade Street Bridge No. 2:** Various maintenance items.

**Waubuno Street Bridge:** Timber replacement for stringers, pier columns, south abutment, and north abutment sills.

The following table summarizes rehabilitation costs, they do not include maintenance or Additional Investigation costs.

**Table 2: Rehabilitation Costs**

STRUCTURE	REHABILITATION	
	YEAR	COST
Seguin Street Bridge	1-5 Years	\$271,000
Seguin Street Pedestrian Bridge	6-10 Years	\$1,047,000
Cascade Street Bridge No. 1	1-5 Years	\$825,000
Cascade Street Bridge No. 2	N/A	\$0
Waubuno Street Bridge	1-5 Years	\$140,000

We trust the above is sufficient for your purposes. If you have any questions or comments regarding the above, please do not hesitate to contact our office.



# Appendix A: Definitions

# Definitions

To convey the results of the visual inspections, defined terms are used to identify deficiencies with respect to condition or performance states. These terms are used in accordance with the OSIM guidelines and are defined below for clarification.

## CONCRETE

**Delamination:** A discontinuity of the surface concrete which is substantially separated but not completely detached from concrete below or above it.

**Efflorescence:** A deposit of salts, usually white and powdery, on the surface of concrete left behind where water percolates through the concrete and dissolves or leaches chemicals from it.

**Honeycombing:** The result of improper or incomplete vibration of the concrete which results in voids being left in the concrete where the mortar failed to completely fill the spaces between the coarse aggregate particles.

**Scaling:** The local flaking, or loss of the surface portion of concrete or mortar as a result of the freeze-thaw deterioration of concrete. It is common in non air-entrained concrete but can also occur in air-entrained concrete in the fully saturated condition. It is prone to occur in poorly finished or overworked concrete where too many fines and not enough entrained air is found near the surface.

**Scour:** The removal of material from the stream bed or bank due to the erosive action of moving water in the stream. Scour can also cause removal of material supporting foundations.

**Spalling:** This is a continuation of the delamination process whereby the actions of external loads, pressure exerted by the corrosion of reinforcement or by the formation of ice in the delaminated area results in the breaking off of delaminated concrete. Spalling may also be caused by overloading of the concrete in compression.

## WOOD

**Wear and Abrasion:** Wear is usually the result of dynamic and/or frictional forces generated by vehicular traffic, coupled with abrasive influx of sand, dirt and debris. It can also result from the friction of ice or water-borne particles against partly or completely submerged members. Abrasion is the deterioration of concrete brought about by vehicles or snow-plough blades scraping against concrete surfaces such as decks, curbs, barrier walls or piers.

**Checks and Splits:** Checks are longitudinal tissue separations along the side grain of wood members occurring across or through the annual growth rings. Splits are similar to checks, with more tissue separations, extending either through the wood member or from the side into the end grain, typically at the ends of the wood member.

**Connection Deficiencies:** connections loosened due to repetitive or dynamic loads, wear or decay of members.

**Cracking, Splintering, Crushing and Shattering:** physical damage as a result of impact loading or overloading of a member.

**Fire and Chemical Damage:** damage resulting from fire or from the use of non-preservative chemicals on the wood surface over a long period of time.

**Insect Damage:** Loss of section caused by tunnelling/boring by insects or larvae.

**Rot or Decay:** decomposition of wood.

**Shakes:** tissue separation that follow the growth rings and are visible at the ends of wood members.

**Splits:** severe separations similar to checks, extending to the ends of wood members.

**Weathering:** this occurs as a result of exposure to the actions of sun, rain, wind, frost and atmospheric pollutants, resulting in the gradual deterioration of the wood.

## STEEL

**Connection Deficiencies:** loose connections, cracking or excessive corrosion of the connector, gusset plate or fasteners.

**Corrosion:** The deterioration of steel by chemical or electro-chemical reaction resulting from exposure to air, moisture, de-icing salts, industrial fumes and other chemicals and contaminants in the environment in which it is placed.

**Cracking:** linear fractures in steel extending partly or completely through the member.

**Permanent Deformations:** bending, buckling, twisting or elongation.

**Patina:** A relatively smooth rust layer, formed on weathering steel, which protects the underlying metal from further corrosion.

## **Appendix B: OSIM Forms**

**Inventory Data:**

Structure Name	<input type="text" value="Cascade Street Bridge No.1"/>		
Main Highway #	<input type="text" value="Cascade Street"/>	On <input checked="" type="checkbox"/> or Under <input type="checkbox"/>	Service on <input type="checkbox"/> Navig. Water <input type="checkbox"/> Non-Navig. Water
		Structure	Structure <input type="checkbox"/> Rail <input checked="" type="checkbox"/> Road <input type="checkbox"/> Ped. <input type="checkbox"/> Other
Location Description	<input type="text" value="0.05 km east of Water Street"/>	Service under:	<input type="checkbox"/> Navig. Water <input checked="" type="checkbox"/> Non-Navig. Water
			<input type="checkbox"/> Rail <input type="checkbox"/> Road <input type="checkbox"/> Ped. <input type="checkbox"/> Other
Owner/Custodian	<input type="text" value="Town of Parry Sound"/>		
MTO Region	<input type="text" value="Northeastern"/>	Latitude	<input n"="" type="text" value="45° 21' 01"/>
		Longitude	<input type="text" value="80° 01' 34" w"=""/>
Regional Engineer	<input type="text"/>	Heritage Designation:	<input checked="" type="checkbox"/> Not Cons. <input type="checkbox"/> Cons./Not App. <input type="checkbox"/> List/Not Desig.
			Desig. <input type="checkbox"/> Desig./Not List <input type="checkbox"/> Desig. & List
MTO Area	<input type="text" value="52 - Huntsville"/>	Hwy Class:	Freeway <input type="checkbox"/> Arterial <input checked="" type="checkbox"/> Collector <input type="checkbox"/> Local <input type="checkbox"/>
Old County	<input type="text" value="44 - Parry Sound"/>	Posted Speed	<input type="text" value="40"/>
		No. of Lanes	<input type="text" value="2"/>
Township	<input type="text" value="452 - McDougall"/>	AADT	<input type="text" value="Unknown"/>
		% Truck	<input type="text" value="Unknown"/>
Structure Type 1	<input type="text" value="Box beam girders"/>		
Structure Material 1	<input type="text" value="Concrete"/>	Traffic Directional Bound	<input type="text" value="N-S"/>
Structure Type 2	<input type="text" value="Concrete Deck"/>		
Structure Material 2	<input type="text" value="Concrete"/>	Inspection Frequency	<input type="text" value="2"/> (years)
Total Deck Length	<input type="text" value="52.9"/> (m)	Inspection Year	<input type="text" value="2022"/>
Overall Str. Width	<input type="text" value="11.2"/> (m)	Inspection Duration	<input type="text" value="2"/> (hrs)
Culvert Length	<input type="text"/> (m)		
Total Deck Area	<input type="text" value="592.5"/> (sq.m)		
Roadway Width	<input type="text" value="8.5"/> (m)	Min. Vertical Clearance	<input type="text"/> (m)
Skew Angle	<input type="text"/> (Degree)	Detour Distance	<input type="text" value="2.2"/> (km)
No. of Spans	<input type="text" value="2"/>	Fill on Structure	<input type="text" value="N/A"/> (m)
Span Lengths	<input type="text" value="26.45, 26.45"/> (m)		
For retaining wall:			
Total Wall Length	<input type="text"/> (m)	Max. Wall Height	<input type="text"/> (m)
Total Wall Area	<input type="text"/> (sq.m)	Ave. Wall Height	<input type="text"/> (m)
		Angle of Backfill	<input type="text"/> (Degrees)

**Historical Data**


Year Built	<input type="text" value="1981"/>	Year of superstruct. Constructed	<input type="text" value="N/A"/>
Last Reg. OSIM Inspection	<input type="text" value="2020"/>	Year of Last Minor Rehab.	<input type="text" value="N/A"/>
Last Enh. OSIM Inspection	<input type="text"/>	Year of Last Major Rehab	<input type="text" value="2009"/>
		Current Load Limit	<input type="text" value="/ /"/> (tonnes)


Work History: (Date/description)	Investigation History: (Date/description)


MTO Site Number:

Field Inspection Information:					
Date of Inspection:	June 30, 2022	Type of Inspection:	<input checked="" type="checkbox"/> Reg. OSIM	<input type="checkbox"/> Enh. OSIM	
Inspected By	Alison Friebel				
Others in Party:	None				
Eng. Access Equipment:	Camera, Tape measure, Hammer				
Special Access Equipment	None				
Weather	Sun/Cloud	Temperature	21 °C		
Additional Investigations Required:			Priority		Estimated Cost
			None	Normal	
Material Condition Survey			X		
Detailed Deck Condition Survey:			X		
Non-destructive Delamination Survey of Asphalt-Covered Deck:			X		
Concrete Substructure Condition Survey:			X		
Detailed Coating Condition Survey:			X		
Detailed Timber Investigation:			X		
Post-Tensioned Strand Investigation:			X		
Underwater Investigation			X		
Fatigue Investigation			X		
Seismic Investigation			X		
Structure Evaluation:			X		
Monitoring			X		
Deformations, Settlements and Movements:			X		
Crack Widths:			X		
RSS Horizontal movements of face:			X		
RSS Vertical movements of overall structure:			X		
RSS Local movements or deterioration of face elements:			X		
RSS Horizontal movements within overall structure:			X		
RSS Vertical movements within overall structure			X		
RSS Lateral earth pressure at the back of facing elements			X		
Investigation Notes:			<b>Total Cost</b>		<b>\$0.00</b>
Overall Structure Notes:					
Recommended Work on Structure	<input type="checkbox"/> None <input checked="" type="checkbox"/> Minor Rehab. <input type="checkbox"/> Major Rehab. <input type="checkbox"/> Replace				
Timing of Recommended Work	<input type="checkbox"/> Urgent <input checked="" type="checkbox"/> 1 to 5 years <input type="checkbox"/> 6 to 10 years				
Overall Comments:	<b>The bridge in in generally good condition. Rehabilitation is recommended for the sidewalk, exterior soffits, and areas of the girder soffit at the girder ends. The asphalt wearing surface is starting to exhibit deterioration with 35% of the total area in fair condition.</b>				
Date of Next inspection:	2024				
Overall Bridge Condition					
% Poor in Deck	% Poor in Beams	% Poor in Substructure	% Poor in Barrier	Bridge Condition Index (BCI or BCIp)	
1%	1%	0%	2%	BCIp 99.07	BCI 73.49
Overall Bridge Sufficiency					
Traffic	Economic	Width	Alignment	Bridge Sufficiency Index (BSI)	
0	3	0	0	70.49	



Element Data:						
Element Group:	Decks		Length:	52.8		
Element Name:	Wearing Surface		Width:	8.5		
Location:	Deck		Height:	0.1		
Material:	Asphalt		Count:			
Element Type:			Total Quantity:	448.8		
Environment:	Severe		Inspected	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	sq.m		333.2	115.6		
Comments: Light ravelling typical. Medium wheel track rutting along wheel lines, typical. 3 light potholes. 40.0m of medium cracking and 11.5m of light cracks generally within wheel lines.						
Recommended Work:		Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:		
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input type="checkbox"/>
Element Photo:						
						
Description of Photo:		Deck Wearing Surface				

Element Data:						
Element Group:	Decks	Length:	52.8			
Element Name:	Deck Top (with Thick Slab)	Width:	11.2			
Location:	Deck	Height:	0.13			
Material:	Concrete	Count:				
Element Type:	Cast-in-Place	Total Quantity:	591.4			
Environment:	Moderate	Inspected	Yes <input type="checkbox"/>	No <input type="checkbox"/>	limited <input checked="" type="checkbox"/>	
Protection System:	Waterproofing and Asphalt					Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	sq.m		591.4			
Comments: Limited inspection. Drawings indicate a concrete distribution slab cast onto the precast concrete girders. Assumed to be in good condition based on wearing surface.						
Recommended Work:		Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:		
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input type="checkbox"/>
Element Photo:						
						
Description of Photo:		Deck Top				

Element Data:						
Element Group:	Decks		Length:	52.9		
Element Name:	Soffit - Thin Slab		Width:	11.2		
Location:			Height:	N/A		
Material:	Concrete and Precast Concrete		Count:			
Element Type:	Cast-in-place ext. soffits, Precast Girders		Total Quantity:	592.5		
Environment:	Benign		Inspected	Yes <input type="checkbox"/>	No <input type="checkbox"/>	limited <input checked="" type="checkbox"/>
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	sq.m		567.5	10.0	15.0	
Comments: Limited inspection due to height. Light scaling, typical. Northeast fascia has 13 x 1.0m medium cracks with efflorescence, 4 areas of severe delamination with exposed rebar (8.0m x 500mm total) and 3 area of severe delamination (3 x 300 x 300mm). Northwest fascia has 14 x 1.0m medium cracks with efflorescence and 1 severe delamination with exposed rebar (3.0m x 300mm). Southwest fascia has 11 x 1.0m light cracks with efflorescence. Southeast fascia has 3 areas of severe delamination with exposed rebar (14.0m x 500mm total), 9 areas of 1.0m light to medium cracking with efflorescence and staining typical.						
Recommended Work:		Rehab: <input checked="" type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:		
Urgent: <input type="checkbox"/>	1-5 Years: <input checked="" type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input type="checkbox"/>
Concrete repairs for the exterior soffit cast-in-place concrete						
<b>Element Photo:</b> 						
<b>Description of Photo:</b>		Soffit Exposed Rebar and Cracks with Efflorescence, Typical				

**Element Photo:**





**Description of Photo:** Soffit Exposed Rebar and Cracks with Efflorescence, Typical

**Element Photo:**



**Description of Photo:** Soffit Exposed Rebar and Cracks with Efflorescence, Typical

Element Data:						
Element Group:	Decks		Length:			
Element Name:	Drainage System		Width:			
Location:	East and West Side		Height:			
Material:	Cast Iron Grate - CSP Pipe		Count:			
Element Type:			Total Quantity:	4		
Environment:	Severe		Inspected	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>
Protection System:	Cast Iron					Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	each		4			
Comments: Light corrosion typical. No evidence of clogging.						
Recommended Work:		Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:		
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input type="checkbox"/>
Element Photo:						
						
Description of Photo:		Deck Drain				

Element Data:						
Element Group:	Sidewalk/Curb	Length:	52.8			
Element Name:	Sidewalks and Medians	Width:	1.8			
Location:	East and West Sides	Height:	0.15			
Material:	Concrete	Count:	1			
Element Type:	Cast-in-place	Total Quantity:	103.0			
Environment:	Severe	Inspected	Yes	<input checked="" type="checkbox"/>	No	<input type="checkbox"/> limited <input type="checkbox"/>
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	sq.m		91.0	2.0	10.0	
Comments: Light scaling, typical. Three general areas of severe delamination. 4 medium to severe spalls along edge of sidewalk.						
Recommended Work:	Rehab:	<input checked="" type="checkbox"/>	Replace:	<input type="checkbox"/>	Maintenance Needs:	
Urgent:	<input type="checkbox"/>	1-5 Years:	<input checked="" type="checkbox"/>	6-10 Years:	<input type="checkbox"/>	None:
					<input type="checkbox"/>	Urgent:
						1 Year:
						2 Year:
Repair concrete						
Element Photo:						
						
Description of Photo: Sidewalk						

Element Photo:




Description of Photo: Sidewalk

Element Photo:



Description of Photo: Sidewalk

Element Data:						
Element Group:	Barriers		Length:	2.4		
Element Name:	Railing Systems		Width:			
Location:	East and West Side		Height:	1.12		
Material:	Aluminum		Count:	50		
Element Type:	4 Rail Metal Railing - Aluminum		Total Quantity:	120.0		
Environment:	Severe		Inspected	Yes <input type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	m		115.6	2.4	2.0	
Comments: West rail has 1 x 2.0m and 1 x 400mm of deformed section and 1 puncture. East rail has isolated areas of medium abrasions and 3 deformations (1 x 100 x 100mm and 2 x 100 x 300mm)						
Recommended Work:		Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:		3 - Railing System Repair
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input checked="" type="checkbox"/>
				Repair railing		
<b>Element Photo:</b>						
						
<b>Description of Photo:</b>		East railing system				



**Element Photo:**




**Description of Photo:** West railing system

**Element Photo:**



**Description of Photo:** West railing system

Element Data:						
Element Group:	Beams/Main Longitudinal Elements	Length:	26.45			
Element Name:	Girders	Width:	1.20			
Location:	Below Deck	Height:	0.84			
Material:	Precast Concrete	Count:	16			
Element Type:	Box Girder	Total Quantity:	298.3			
Environment:	Benign	Inspected	Yes <input type="checkbox"/>	No <input type="checkbox"/>	limited <input checked="" type="checkbox"/>	
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	sq.m		298.3	4.0	2.0	
Comments: Light scaling, typical North end of girder at abutment has 5 areas of 500 x 500mm severe delamination. Center span has several areas of 100 x 100mm delaminations. South end of girder at abutment has 2 areas of 300 x 300mm severe delaminations. Light rebar staining at girder ends typical.						
Recommended Work:		Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:		
Urgent: <input type="checkbox"/>	1-5 Years: <input checked="" type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input type="checkbox"/>
Repair concrete						
<b>Element Photo:</b> 						
Description of Photo:		Girder Soffit				

Element Photo:




Description of Photo: Girder Soffit

Element Photo:



Description of Photo: Girder Soffit

Element Data:						
Element Group:	Abutments		Length:			
Element Name:	Abutment Walls		Width:	11.1		
Location:	North and South Ends		Height:	4.3		
Material:	Concrete		Count:	2		
Element Type:	Cast-in-place		Total Quantity:	95.5		
Environment:	Benign		Inspected	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	sq.m		81.9	13.5	0.1	
Comments: Light scaling, typical, with medium scaling generally within 1 m from bottom of wall. North abutment has 2 x 3.0m vertical medium crack on older concrete section. South abutment has 1 x 3.0m vertical medium crack and 2 x 300mm vertical light cracks. 100 x 300 x25mm medium spall with medium corroded rebar at bottom of south abutment.						
Recommended Work:		Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:		
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input type="checkbox"/>
<div style="border: 1px solid black; padding: 5px;"> <b>Element Photo:</b>     </div>						
Description of Photo:		North Abutment				

Element Photo:




Description of Photo: South abutment

Element Photo:



Description of Photo: South abutment

Element Data:						
Element Group:	Abutments	Length:	6.7			
Element Name:	Wingwalls	Width:				
Location:	All Quadrants	Height:	4.3			
Material:	Concrete	Count:	4			
Element Type:	Cast-in-place	Total Quantity:	114.4			
Environment:	Benign	Inspected	Yes <input type="checkbox"/>	No <input type="checkbox"/>	limited <input checked="" type="checkbox"/>	
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	sq.m		114.3	0.1		
Comments: Northwest and northeast walls have light map cracking, typical. Northeast wall has light erosion at base of wall. Southeast wall has light scaling, typical. Southwest wall has a 300mm medium crack.						
Recommended Work:	Rehab: <input type="checkbox"/>		Replace: <input type="checkbox"/>		Maintenance Needs:	
	Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/> 2 Year: <input type="checkbox"/>
<b>Element Photo:</b>						
						
Description of Photo: Southeast wingwall						

Element Photo:



Description of Photo: Southwest wingwall

Element Photo:



Description of Photo: Northeast wingwall


Element Data:						
Element Group:	Piers	Length:	1.0			
Element Name:	Shafts/Columns/Pile Bents	Width:	9.0			
Location:	Center Pier	Height:	6.2			
Material:	Concrete	Count:	1			
Element Type:	Cast-in-place	Total Quantity:	213.0			
Environment:	Benign	Inspected	Yes <input type="checkbox"/>	No <input type="checkbox"/>	limited <input checked="" type="checkbox"/>	
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	sq.m		123.0			
Comments: Light scaling typical. South side has 1-2.0m and 2-1.0m vertical light cracks near bottom of pier. Steel angle nosing at east side has light corrosion, typical.						
Recommended Work:	Rehab: <input type="checkbox"/>		Replace: <input type="checkbox"/>		Maintenance Needs:	
	Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/> 2 Year: <input type="checkbox"/>


**Element Photo:**





**Description of Photo:** Pier



Element Data:						
Element Group:	Piers	Length:				
Element Name:	Bearings	Width:				
Location:	Center Pier	Height:				
Material:	Elastomeric	Count:	8			
Element Type:		Total Quantity:	8			
Environment:	Moderate	Inspected	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>	limited <input type="checkbox"/>	
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	each		8			
Comments: <b>Not accessible for inspection. Assumed to be in good condition.</b>						
Recommended Work:		Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:		
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input type="checkbox"/>
<b>Element Photo:</b>						
						
<b>Description of Photo:</b> Pier Bearings						

Element Data:						
Element Group:	Retaining Walls	Length:	10.0			
Element Name:	Walls	Width:				
Location:	SW Embankment	Height:	1.2			
Material:	Gabion Baskets	Count:	1			
Element Type:	Rock	Total Quantity:	12.0			
Environment:	Benign	Inspected	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>	
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	sq.m		12.0			
Comments: No evidence of settlement or sliding. Minor deviations in horizontal alignment.						
Recommended Work:		Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:		
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input type="checkbox"/>
Element Photo:						
						
Description of Photo:		Retaining Wall				

Element Data:						
Element Group:	Embankments & Streams		Length:			
Element Name:	Streams and Waterways		Width:			
Location:	East and West		Height:			
Material:	Bedrock		Count:	All		
Element Type:			Total Quantity:			
Environment:	Benign		Inspected	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	all	X				
Comments: <b>No observed defects.</b>						
Recommended Work:		Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:		
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input type="checkbox"/>
<b>Element Photo:</b> 						
<b>Description of Photo:</b> Streams and Waterways						

Element Data:						
Element Group:	Embankments & Streams		Length:			
Element Name:	Embankments		Width:			
Location:	SW, SE and NW Quadrants		Height:			
Material:	Trees, Shrubs and Earth		Count:	3		
Element Type:	Vegetation		Total Quantity:	3		
Environment:	Benign		Inspected	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	each		3			
Comments: All 3 embankments are heavily vegetated. Light erosion on northwest quadrant. No embankment element present on northeast so it is part of structure.						
Recommended Work:		Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:		
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input type="checkbox"/>
Element Photo:						
						
Description of Photo:		SW Embankment				


Element Photo:



Description of Photo: NW Embankment

Element Photo:

Description of Photo:

Element Data:						
Element Group:	Approaches		Length:	6.9		
Element Name:	Wearing Surface		Width:	8.5		
Location:	North and South		Height:	0.10		
Material:	Asphalt		Count:	2		
Element Type:			Total Quantity:	116.5		
Environment:	Severe		Inspected	Yes <input type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	sq.m		116.5	13.7		
Comments: Light raveling, typical. North approach has 8.0m of light cracks in wheel rut and 150x150mm loss of bond around catch basin. South has 3.5m of light cracks. Light to medium rutting along wheel lines.						
Recommended Work:		Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:		
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input type="checkbox"/>
Element Photo:						
						
Description of Photo:		South approach				

Element Photo:




Description of Photo: North approach


Element Photo:



Description of Photo: North approach

Element Data:							
Element Group:	Approaches		Length:	6.9			
Element Name:	Approach Slab		Width:	8.5			
Location:	North and south		Height:	0.26			
Material:	Concrete		Count:	2			
Element Type:	Solid Slab		Total Quantity:	116.5			
Environment:	Benign		Inspected	Yes <input type="checkbox"/>	No <input type="checkbox"/>	limited <input checked="" type="checkbox"/>	
Protection System:	Asphalt Wearing Surface						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*		
	sq.m		116.5				
Comments: Approach slabs are assumed to be in good condition based on asphalt condition.							
Recommended Work:		Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:			
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input type="checkbox"/>	
Element Photo:							
							
Description of Photo:		Approach slab					



Element Data:						
Element Group:	Approaches	Length:	46.0			
Element Name:	Barrier	Width:				
Location:	NW, SE and SW Quadrants	Height:				
Material:	Steel	Count:	1			
Element Type:	Steel beam Guide Rail on Steel Posts	Total Quantity:	46.0			
Environment:	Severe	Inspected	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>	
Protection System:	Galvanized					Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	8 - Pedestrian / vehicular hazard
	m	8.0	22.0	12.0	4.0	
Comments: Northwest is in excellent condition. Remaining rails have localized light corrosion typical. No guide rail northeast approach. Southwest end termination has medium corrosion, full length deformations and 4 rotten wood posts. Southwest W-beam has 2.5m of deformations and two 300x300mm deformations. The end terminal has deficient height and end block is rotated sideways. Southeast has abrasion deformations and it's bridge connection has deficient height.						
Recommended Work:	Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:	3 - Railing System Repair		
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input checked="" type="checkbox"/>
				Replaced damaged rail sections, rotten wood post and install end treatments at the south approach.		
<b>Element Photo:</b>						
						
<b>Description of Photo:</b> Approach Barrier						

**Element Photo:**




**Description of Photo:** Approach Barrier

**Element Photo:**



**Description of Photo:** Approach Barrier

Element Data:						
Element Group:	Approaches	Length:	6.9			
Element Name:	Curb and Gutters	Width:	0.3			
Location:	West Side	Height:	0.14			
Material:	Concrete	Count:	2			
Element Type:	Curb	Total Quantity:	6.0			
Environment:	Severe	Inspected	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>	
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	sq.m		6.0			
Comments: Light scaling and abrasions typical. Northwest curb has 2 light spalls.						
Recommended Work:		Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:		
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input type="checkbox"/>
Element Photo:						
						
Description of Photo: Northwest curb						


Element Photo:



Description of Photo: Southwest curb

Element Photo:

Description of Photo:

Element Data:						
Element Group:	Approaches		Length:	6.85		
Element Name:	Sidewalk/Curb		Width:	1.8		
Location:	East Side		Height:	0.14		
Material:	Concrete		Count:	2		
Element Type:	Sidewalk		Total Quantity:	26.6		
Environment:	Moderate		Inspected	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	sq.m		26.1	0.5		
Comments: Light scaling typical. Abrasion and wear along sidewalk edge. Southeast has 2-1.0m diagonal light cracks and northeast has 1-1.8m medium crack at joint.						
Recommended Work:		Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:		
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input type="checkbox"/>
Element Photo:						
						
Description of Photo: Approach sidewalk						

**Element Photo:**



**Description of Photo:** Approach Sidewalk

**Element Photo:**

**Description of Photo:**

Repair and Rehabilitation Required:		Priority				Estimated Structural Cost
Element <sup>1</sup>	Repair and Rehabilitation Required <sup>2</sup>	6 to 10 Years	1 to 5 Years	Within 1 Year	Urgent	
Structure	Demolition					
Structure	Replacement					
OR						
Deck	Rehab. = Repair exterior soffit concrete		X			\$150,000.00
Sidewalk/Curb	Rehab. = Repair delaminated areas		X			\$125,000.00
Barrier	Rehab. =					
Joints	Rehab. =					
Beams	Rehab. = Repair soffit concrete		X			\$75,000.00
Abutment	Rehab. =					
Pier	Rehab. =					
Other	Asphalt Wearing Surface and Waterproofing					\$100,000.00
Estimated Rehabilitated or Replacement Structure Dimensions <sup>3</sup>						
Total Deck Length (m)		Overall Str. Width (m)		Total Structural Cost		\$450,000.00

1 - Indicate specific costs for structure replacement OR for rehabilitation under the given headings.

2 - Give a very brief description of the rehabilitation work required.

3 - Estimated structure dimensions after completion of the proposed work - if it is expected to change.

Associated Work	Comments	Estimated Associated Work Cost
Approaches	Replace damaged rail sections, install end treatment	\$10,000.00
Detours		
Traffic Control		\$80,000.00
Utilities		
Other	Engineering and Contingency	\$100,000.00
	General, Mobilization/Demobilization, Access, General	\$185,000.00
Total Associated Work Cost		\$375,000.00

Total Construction Cost	\$825,000.00
-------------------------	--------------

Justification:
Rehabilitation is recommended for the sidewalk top and front face surfaces, exterior soffits, and areas of the girder soffit at the girder ends. The asphalt wearing surface is starting to exhibit deterioration with 35% of the total area in fair condition and could be considered for replacing with new asphalt with waterproofing membrane, costs include this work.

**Inventory Data:**

Structure Name	<b>Cascade Street Bridge No.2</b>		
Main Highway #	<b>Cascade Street</b>	On <input checked="" type="checkbox"/> or Under <input type="checkbox"/>	Service on Structure <input type="checkbox"/> Navig. Water <input type="checkbox"/> Non-Navig. Water <input type="checkbox"/> Rail <input checked="" type="checkbox"/> Road <input type="checkbox"/> Ped. <input type="checkbox"/> Other <input type="checkbox"/>
Location Description	0.019km east of Water St.	Service under:	<input type="checkbox"/> Navig. Water <input checked="" type="checkbox"/> Non-Navig. Water <input type="checkbox"/> Rail <input type="checkbox"/> Road <input checked="" type="checkbox"/> Ped. <input type="checkbox"/> Other
Owner/Custodian	Town of Parry Sound		
MTO Region	North Eastern	Latitude	45° 21' 02"N Longitude 80° 01' 35"W
Regional Engineer		Heritage Designation:	<input checked="" type="checkbox"/> Not Cons. <input type="checkbox"/> Cons./Not App. <input type="checkbox"/> List/Not Desig. Desig. <input type="checkbox"/> Desig./Not List <input type="checkbox"/> Desig. & List
MTO Area	<b>52 - Huntsville</b>	Hwy Class:	Freeway <input type="checkbox"/> Arterial <input type="checkbox"/> Collector <input checked="" type="checkbox"/> Local <input type="checkbox"/>
Old County	<b>44 - Parry Sound</b>	Posted Speed	<b>40</b> No. of Lanes <b>2</b>
Township	<b>452 - McDougall</b>	AADT	<b>Unknown</b> % Truck <b>Unknown</b>
Structure Type 1	<b>Rigid Frame Vertical Leg</b>		
Structure Material 1	<b>Concrete</b>	Traffic Directional Bound	<b>N-S</b>
Structure Type 2	<b>Concrete Deck</b>		
Structure Material 2	<b>Concrete</b>	Inspection Frequency	<b>2</b> (years)
Total Deck Length	<b>11.5</b> (m)	Inspection Year	<b>2022</b>
Overall Str. Width	<b>11.2</b> (m)	Inspection Duration	<b>2</b> (hrs)
Culvert Length			
Total Deck Area	<b>128.8</b> (sq.m)		
Roadway Width	<b>8.0</b> (m)	Min. Vertical Clearance	<b>3.6</b> (m)
Skew Angle	<b>10</b> (Degree)	Detour Distance	<b>2.4</b> (km)
No. of Spans	<b>1</b>	Fill on Structure	<b>0</b> (m)
Span Lengths	<b>10.0</b> (m)		
For retaining wall:			
Total Wall Length	<b>6.0</b> (m)	Max. Wall Height	<b>2.8</b> (m)
Total Wall Area	<b>16.8</b> (sq.m)	Ave. Wall Height	<b>2.8</b> (m)
		Angle of Backfill	

**Historical Data**


Year Built	<b>1984</b>	Year of superstruct. Constructed	<b>N/A</b>
Last Reg. OSIM Inspection	<b>2020</b>	Year of Last Minor Rehab.	<b>N/A</b>
Last Enh. OSIM Inspection		Year of Last Major Rehab	<b>Unknown</b>
		Current Load Limit	<input type="text"/> / <input type="text"/> / <input type="text"/> (tonnes)


Work History: (Date/description)	Investigation History: (Date/description)




MTO Site Number:

Field Inspection Information:					
Date of Inspection:	June 30, 2021	Type of Inspection:	<input checked="" type="checkbox"/> Reg. OSIM	<input type="checkbox"/> Enh. OSIM	
Inspected By	Alison Friebel				
Others in Party:	None				
Eng. Access Equipment:	Hammer, Camera and Tape measure				
Special Access Equipment	None				
Weather	Sun/clouds	Temperature	15 °C		
Additional Investigations Required:			Priority		Estimated Cost
			None	Normal	
Material Condition Survey			X		
Detailed Deck Condition Survey:			X		
Non-destructive Delamination Survey of Asphalt-Covered Deck:			X		
Concrete Substructure Condition Survey:			X		
Detailed Coating Condition Survey:			X		
Detailed Timber Investigation:			X		
Post-Tensioned Strand Investigation:			X		
Underwater Investigation			X		
Fatigue Investigation			X		
Seismic Investigation			X		
Structure Evaluation:			X		
Monitoring			X		
Deformations, Settlements and Movements:			X		
Crack Widths:			X		
RSS Horizontal movements of face:			X		
RSS Vertical movements of overall structure:			X		
RSS Local movements or deterioration of face elements:			X		
RSS Horizontal movements within overall structure:			X		
RSS Vertical movements within overall structure			X		
RSS Lateral earth pressure at the back of facing elements			X		
Investigation Notes:			<b>Total Cost</b>		<b>\$0.00</b>
Overall Structure Notes:					
Recommended Work on Structure	<input type="checkbox"/> None <input checked="" type="checkbox"/> Minor Rehab. <input type="checkbox"/> Major Rehab. <input type="checkbox"/> Replace				
Timing of Recommended Work	<input type="checkbox"/> Urgent <input checked="" type="checkbox"/> 1 to 5 years <input type="checkbox"/> 6 to 10 years				
Overall Comments:	<b>The bridge is in generally good condition. There is some approach asphalt deterioration. The north approach barriers to bridge connection are substandard and should be considered to be upgraded to meet the current standard, this was considered as a maintenance item.</b>				
Date of Next inspection:	2024				
Overall Bridge Condition					
% Poor in Deck	% Poor in Beams	% Poor in Substructure	% Poor in Barrier	Bridge Condition Index (BCI or BCIp)	
1%	0%	2%	2%	BCIp 98.89	BCI 71.94
Overall Bridge Sufficiency					
Traffic	Economic	Width	Alignment	Bridge Sufficiency Index (BSI)	
0	3	0	0	68.94	

Element Data:						
Element Group:	Decks		Length:	11.2		
Element Name:	Wearing Surface		Width:	8.5		
Location:	Deck		Height:	0.09		
Material:	Asphalt		Count:	1		
Element Type:			Total Quantity:	95.2		
Environment:	Severe		Inspected	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	sq.m		75.7	18.0	1.5	
Comments: Light raveling, typical. Light to medium rutting along wheel lines, typical. 12 m of medium cracking along centerline, and a 6 m severe crack. 8.5m medium cracks at both abutment. 1.2 m x 800mm medium loss of bond at centerline at north abutment.						
Recommended Work:		Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:		
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input type="checkbox"/>
Element Photo:						
						
Description of Photo:		Deck wearing surface				

Element Data:						
Element Group:	Decks	Length:	11.2			
Element Name:	Deck Top (with Thick Slab)	Width:	8.5			
Location:	Deck	Height:	Varies			
Material:	Concrete	Count:	1			
Element Type:	Cast-in-Place	Total Quantity:	95.2			
Environment:	Moderate	Inspected	Yes <input type="checkbox"/>	No <input type="checkbox"/>	limited <input checked="" type="checkbox"/>	
Protection System:	Asphalt					Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	sq.m		95.2			
Comments: Limited inspection. Assumed to be in good condition based on wearing surface.						
Recommended Work:		Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:		
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input type="checkbox"/>
<p><b>Element Photo:</b></p> 						
Description of Photo:		Deck top				

Element Data:						
Element Group:	Decks		Length:	10.2		
Element Name:	Soffit - Thick Slab		Width:	11.2		
Location:			Height:	N/A		
Material:	Concrete		Count:	1.0		
Element Type:	Cast-in-Place		Total Quantity:	113.7		
Environment:	Benign		Inspected	Yes <input type="checkbox"/>	No <input type="checkbox"/>	limited <input checked="" type="checkbox"/>
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	sq.m		107.7	3.0	3.0	
Comments: Limited inspection due to height. Light scaling, typical. 14.0m of medium cracks with efflorescence extending to 2m away from abutments. 12.0m of medium cracks. 12.0m of light cracks along centerline. Five 300mm light cracks on west fascia. Four light cracks on east fascia. Isolated areas of light staining.						
Recommended Work:		Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:		
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input type="checkbox"/>
<b>Element Photo:</b>						
						
<b>Description of Photo:</b> Soffit typical						

**Element Photo:**




**Description of Photo:** Cracks with Efflorescence

**Element Photo:**



**Description of Photo:** Soffit fascia

Element Data:						
Element Group:	Decks		Length:			
Element Name:	Drainage System		Width:			
Location:			Height:			
Material:			Count:			
Element Type:			Total Quantity:	N/A		
Environment:	Severe		Inspected	Yes <input type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	each					
Comments: No deck drains, drainage provided by surface sheet flow. The abutment walls have 8 drain pipes with isolated areas of light debris build up at bottom of drains.						
Recommended Work:		Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:		
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input type="checkbox"/>
Element Photo:						
						
Description of Photo: Abutment Wall Drain Pipe, Typical						

Element Data:						
Element Group:	Sidewalk/Curb	Length:	11.2			
Element Name:	Sidewalks and Medians	Width:	1.4			
Location:	East and West Side of Deck	Height:	0.14			
Material:	Concrete	Count:	2			
Element Type:	Cast-in-place	Total Quantity:	33.4			
Environment:	Severe	Inspected	Yes	<input checked="" type="checkbox"/>	No	<input type="checkbox"/> limited <input type="checkbox"/>
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	sq.m		33.0	0.4		
Comments: Light scaling typical. 1.5m medium crack 2.0m south of north joint. 2.0m of light cracks at northeast quadrant. East sidewalk has light abrasions and areas of rust staining. West sidewalk has one 400mm light crack. West sidewalk has sand and debris deposits along raised curb.						
Recommended Work:	Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:	2 - Bridge Cleaning		
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input checked="" type="checkbox"/>	2 Year: <input type="checkbox"/>
				Remove debris build-up		

**Element Photo:**



**Description of Photo:** East sidewalk

**Element Photo:**




**Description of Photo:** West sidewalk

**Element Photo:**



**Description of Photo:** East sidewalk light cracks



Element Data:						
Element Group:	Barriers		Length:	15.0		
Element Name:	Railing Systems		Width:			
Location:	East and West Side		Height:	1.12		
Material:	Aluminum and Concrete		Count:	2		
Element Type:	4 Rail Metal Railing - Aluminum		Total Quantity:	30.0		
Environment:	Severe		Inspected	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	m		15.5	14.0	0.5	
Comments: East side has localized abrasion and localized deformations on all 4 rails the entire length. Two end caps missing at north ends. One 50mm x 50mm deformation on east rail. Concrete barriers have light scaling typical. South east concrete barrier has isolated areas of light spalls at corners. Four light cracks at northeast concrete barrier.						
Recommended Work:		Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:		3 - Railing System Repair
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input checked="" type="checkbox"/>
				Replace missing end caps.		
<b>Element Photo:</b> 						
<b>Description of Photo:</b>		Railing System, Abrasions, Typical				

**Element Photo:**



**Description of Photo:** Concrete End Wall, Typical

**Element Photo:**



**Description of Photo:** East Railing System

Element Data:						
Element Group:	Abutments		Length:			
Element Name:	Abutment Walls		Width:	11.3		
Location:	North and South		Height:	5.1		
Material:	Concrete		Count:	2		
Element Type:	Cast-in-place		Total Quantity:	115.6		
Environment:	Benign		Inspected	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	sq.m		106.7	5.0	5.0	
Comments: Light scaling, typical. Light erosion at both ends of the footings. 4.0m of light cracking. 15.0m of medium cracking. 800mm of severe cracking at center of footing. Bottom of south wall has localized area of very severe scouring with a 500mm x 300mm x 100mm deep void with water churning within the void. 300mm x 100mm light scouring @ northwest corner. Severe scaling 200mm from bottom of wall for the full length on bridge on both sides. 400mm x 200mm spall at south footing.						
Recommended Work:	Rehab: <input type="checkbox"/> Replace: <input type="checkbox"/>		Maintenance Needs:	8 - Concrete Repair		
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input checked="" type="checkbox"/>
				Repair concrete void.		

**Element Photo:**



**Description of Photo:** South Abutment

**Element Photo:**



**Description of Photo:** Northwest Corner

**Element Photo:**



**Description of Photo:** South Abutment, Note Void at End of Footing

Element Data:						
Element Group:	Abutments	Length:	6.7			
Element Name:	Wingwalls	Width:				
Location:	All Quadrants	Height:	4.9			
Material:	Concrete	Count:	4			
Element Type:	Cast-in-place	Total Quantity:	132.4			
Environment:	Benign	Inspected	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>	
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	sq.m		126.9	4.5	1.0	
Comments: Light scaling typical. Southwest wingwall has light diagonal 2.0m cracks. Southeast has 1.5m of medium vertical cracking at the center of the wall. All wingwalls have a severe 500mm long horizontal crack the width of the abutment wall at the top of wingwall at bearing seat. Medium scaling on the southeast wingwall 600mm(H) x 6.0m(L) and 2.0m light vertical crack and 2 x 60mm x 20mm medium scaling.						
Recommended Work:		Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:		
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input type="checkbox"/>

**Element Photo:**



**Description of Photo:** Northwest wingwall

Element Photo:




Description of Photo: Wingwall

Element Photo:



Description of Photo: Northeast wingwall


Element Data:						
Element Group:	Retaining Walls	Length:	15.0			
Element Name:	Walls	Width:				
Location:	Southwest Quadrant	Height:	1.8			
Material:	Mortar and Stone	Count:	1			
Element Type:		Total Quantity:	27.0			
Environment:	Benign	Inspected	Yes <input type="checkbox"/>	No <input type="checkbox"/>	limited <input checked="" type="checkbox"/>	
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	sq.m		14.4	12.2	0.5	
Comments: Retaining wall is possibly part of the Cascade Street Generating Station operated by Bracebridge Generation. Light to medium loss of mortar and stones typical. Efflorescence deposits throughout emanating from the mortar. Severe scouring 1.5m x 300 x 300mm and medium scouring 0.6 x 75 x 250mm at bottom center of wall with loss of mortar and stones.						
Recommended Work:		Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:		18 - Other Maintenance
Urgent: <input type="checkbox"/>		1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/> 2 Year: <input checked="" type="checkbox"/>
				Repair scouring at bottom of retaining wall. Confirm if this element belongs to the generation facility prior to undertaking repairs.		
<b>Element Photo:</b>						
						
Description of Photo:		Retaining wall				

Element Data:						
Element Group:	Embankments & Streams		Length:			
Element Name:	Streams and Waterways		Width:			
Location:	East and West		Height:			
Material:	Exposed Bedrock		Count:			
Element Type:			Total Quantity:	All		
Environment:	Benign		Inspected	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	all	X				

Comments: No observed defects. Channel consists of exposed bedrock and is a spillway channel for an upstream dam.


Recommended Work:	Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:			
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input type="checkbox"/>

**Element Photo:**



Description of Photo: Waterway



Element Data:							
Element Group:	Embankments & Streams		Length:				
Element Name:	Embankments		Width:				
Location:	NE, SW, NW Quadrants		Height:				
Material:	Vegetation, shrubs and rocks		Count:	3			
Element Type:			Total Quantity:	3			
Environment:	Benign		Inspected	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>	
Protection System:	Rip Rap					Performance Deficiencies	
Condition Data:	Units	Excellent	Good	Fair	Poor*		
	each	2	1				
Comments: Northeast embankment has light undermining at waterline. Southwest embankment has light scouring at waterline. No other observed defects.							
Recommended Work:		Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:			
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input type="checkbox"/>	
Element Photo:							
							
Description of Photo:		Northeast embankment					

Element Photo:





Description of Photo: Southwest embankment


Element Photo:




Description of Photo: Northwest embankment

Element Data:						
Element Group:	Embankments & Streams		Length:			
Element Name:	Slope Protection		Width:			
Location:	NE and NW Quadrants		Height:			
Material:	150mm - 300mm Stone		Count:	2		
Element Type:	Rip Rap		Total Quantity:	2		
Environment:	Benign		Inspected	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	each	2				
Comments: <b>No observed defects.</b>						
Recommended Work:		Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:		
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input type="checkbox"/>
<b>Element Photo:</b>						
						
<b>Description of Photo:</b>		Slope Protection				

Element Data:							
Element Group:	Accessories		Length:				
Element Name:	Signs		Width:				
Location:	Northwest Approach		Height:				
Material:	Steel		Count:	1			
Element Type:			Total Quantity:	1			
Environment:	Benign		Inspected	Yes	<input checked="" type="checkbox"/>	No	<input type="checkbox"/> limited <input type="checkbox"/>
Protection System:							Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*		
	each		1				
Comments: Bridge freezes sign is in good condition. Tab portion has light map cracking							
Recommended Work:		Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:			
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input type="checkbox"/>	
Element Photo:							
							
Description of Photo:		Sign					

Element Data:						
Element Group:	Accessories		Length:			
Element Name:	Utilities		Width:			
Location:	Within North Sidewalk		Height:			
Material:	PVC		Count:	2		
Element Type:	Rigid Conduit		Total Quantity:	2		
Environment:	Benign		Inspected	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>	limited <input type="checkbox"/>
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	each		2			
Comments: As-built drawings indicate 2-75mm diameter conduits are within the east sidewalk, they are not visible.						
Recommended Work:		Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:		
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input type="checkbox"/>
Element Photo:						
						
Description of Photo:		Utilities				

Element Data:						
Element Group:	Approaches		Length:	6.0		
Element Name:	Wearing Surface		Width:	8.5		
Location:	North and South		Height:	0.10		
Material:	Asphalt		Count:	2		
Element Type:			Total Quantity:	102.0		
Environment:	Severe		Inspected	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	sq.m		89.0	10.0	3.0	
Comments: North approach has 21.0m of medium cracking and 0.5 x 6.0m of loss of bond. South approach has 8.5 of medium cracking.						
Recommended Work:	Rehab: <input type="checkbox"/> Replace: <input type="checkbox"/>		Maintenance Needs:	12 - Bridge Surface Repair		
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input checked="" type="checkbox"/>
				Repair asphalt		
Element Photo:						
						
Description of Photo: North Approach						

**Element Photo:**



**Description of Photo:** South Approach

**Element Photo:**

**Description of Photo:**

Element Data:						
Element Group:	Approaches	Length:	52.0			
Element Name:	Barrier	Width:				
Location:	All Quadrants	Height:				
Material:	Steel, Timber, Concrete, Aluminum	Count:				
Element Type:	Steel Beam Guide Rail	Total Quantity:	52.0			
Environment:	Severe	Inspected	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>	
Protection System:	Galvanized					Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	m		47.5	4.0	0.5	
Comments: Northeast rail has substandard connection to bridge, approach rail has 1 missing bolt, three posts with 50x50mm splintering and localized light abrasions. Northwest rail has substandard connection to bridge, with medium corrosion towards the end of the rail. Southeast rail concrete wall has light scaling, typical. An approach to the connection upgrades would be to install the additional transition posts, then schedule the full upgrades for a future rehabilitation, costs provided are for the post upgrades only.						
Recommended Work:	Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:	3 - Railing System Repair		
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input checked="" type="checkbox"/>
				Upgrade NE and NW barrier to bridge connection		

**Element Photo:**



**Description of Photo:** Northeast approach barrier



**Element Photo:**





**Description of Photo:** Northwest approach barrier

**Element Photo:**



**Description of Photo:** Southeast approach barrier

Element Data:						
Element Group:	Approaches		Length:	6.0		
Element Name:	Curb and Gutters		Width:			
Location:	All Quadrants		Height:	0.2		
Material:	Concrete		Count:	4		
Element Type:			Total Quantity:	23.2		
Environment:	Severe		Inspected	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	sq.m		23.2			
Comments: Light scaling, typical. Some debris along gutters, no obstruction to drainage. Light abrasions along curb edges typical and light spall at southwest curb.						
Recommended Work:		Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:		
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input type="checkbox"/>
<b>Element Photo:</b> 						
<b>Description of Photo:</b> Approach curb						

Element Data:						
Element Group:	Approaches		Length:	6.0		
Element Name:	Sidewalk/Curb		Width:	1.4		
Location:	NE and SE Quadrants		Height:	0.14		
Material:	Concrete		Count:	2		
Element Type:			Total Quantity:	32.4		
Environment:	Severe		Inspected	Yes <input type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	sq.m		32.4			
Comments: Light scaling, typical. No other observed defects.						
Recommended Work:		Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:		
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input type="checkbox"/>
<b>Element Photo:</b> 						
<b>Description of Photo:</b> Approach sidewalk						

Repair and Rehabilitation Required:		Priority				Estimated Structural Cost
Element <sup>1</sup>	Repair and Rehabilitation Required <sup>2</sup>	6 to 10 Years	1 to 5 Years	Within 1 Year	Urgent	
Structure	Demolition					
Structure	Replacement					
OR						
Deck	Rehab. =					
Sidewalk/Curb	Rehab. =					
Barrier	Rehab. =					
Joints	Rehab. =					
Beams	Rehab. =					
Abutment	Rehab. =					
Pier	Rehab. =					
Other	Maintenance = N Approach Barriers					\$5,000.00
Estimated Rehabilitated or Replacement Structure Dimensions <sup>3</sup>						
Total Deck Length (m)		Overall Str. Width (m)		Total Structural Cost		\$5,000.00

1 - Indicate specific costs for structure replacement OR for rehabilitation under the given headings.

2 - Give a very brief description of the rehabilitation work required.

3 - Estimated structure dimensions after completion of the proposed work - if it is expected to change.

Associated Work	Comments	Estimated Associated Work Cost
Approaches		
Detours		
Traffic Control		
Utilities		
Other		
Total Associated Work Cost		\$0.00

Total Construction Cost	\$5,000.00
-------------------------	------------

**Justification:**

The north approach barriers to bridge connection are substandard and should be considered to be upgraded to meet the current standard, this was considered as a maintenance item. An approach to the connection upgrades would be to install the additional transition posts, then schedule the full upgrades for a future rehabilitation, costs provided are for the post upgrades only.

**Inventory Data:**

Structure Name	<b>Seguin River Pedestrian Bridge</b>		
Main Highway #	<b>Parry Sound Fitness Trail</b>	On <input checked="" type="checkbox"/> or Under <input type="checkbox"/> Structure	Service on Structure: <input type="checkbox"/> Navig. Water <input type="checkbox"/> Non-Navig. Water <input type="checkbox"/> Rail <input type="checkbox"/> Road <input checked="" type="checkbox"/> Ped. <input type="checkbox"/> Other
Location Description	0.1km South of Seguin Street	Service under:	<input checked="" type="checkbox"/> Navig. Water <input type="checkbox"/> Non-Navig. Water <input type="checkbox"/> Rail <input type="checkbox"/> Road <input type="checkbox"/> Ped. <input type="checkbox"/> Other
Owner/Custodian	Town of Parry Sound		
MTO Region	Northeastern	Latitude	45° 20' 33" N Longitude 80° 01' 53" W
Regional Engineer		Heritage Designation:	<input checked="" type="checkbox"/> Not Cons. <input type="checkbox"/> Cons./Not App. <input type="checkbox"/> List/Not Desig. Desig. <input type="checkbox"/> Desig./Not List <input type="checkbox"/> Desig. & List
MTO Area	<b>52 - Huntsville</b>	Hwy Class:	Freeway <input type="checkbox"/> Arterial <input type="checkbox"/> Collector <input type="checkbox"/> Local <input checked="" type="checkbox"/>
Old County	<b>44 - Parry Sound</b>	Posted Speed	<b>0</b> No. of Lanes <b>0</b>
Township	<b>452 - McDougall</b>	AADT	<b>0</b> % Truck <b>0</b>
Structure Type 1	<b>Timber deck</b>	Traffic Directional Bound	<b>E-W</b>
Structure Material 1	<b>Timber</b>	Inspection Frequency	<b>2</b> (years)
Structure Type 2	<b>Steel Frame</b>	Inspection Year	<b>2022</b>
Structure Material 2	<b>Steel</b>	Inspection Duration	<b>2</b> (hrs)
Total Deck Length	<b>96.5</b> (m)	Min. Vertical Clearance	
Overall Str. Width	<b>4.6</b> (m)	Detour Distance	<b>N/A</b> (km)
Culvert Length	<b>0</b> (m)	Fill on Structure	
Total Deck Area	<b>332.9</b> (sq.m)	Span Lengths	<b>3.4, 3.8, 4.0, 4.0, 3.9, 3.8, 3.8, 3.75, 3.65, 22.6, 14.3, 25.5 (east to west)</b> (m)
Roadway Width	<b>3.45</b> (m)	For retaining wall:	
Skew Angle	<b>0</b> (Degree)	Total Wall Length	
No. of Spans	<b>12</b>	Total Wall Area	
		Max. Wall Height	
		Ave. Wall Height	
		Angle of Backfill	

**Historical Data**

Year Built	<b>1920</b>	Year of superstruct. Constructed	<b>N/A</b>
Last Reg. OSIM Inspection	<b>2020</b>	Year of Last Minor Rehab.	<b>N/A</b>
Last Enh. OSIM Inspection		Year of Last Major Rehab	<b>N/A</b>
		Current Load Limit	<input type="text"/> / <input type="text"/> / <input type="text"/> (tonnes)

<b>Work History: (Date/description)</b>	<b>Investigation History: (Date/description)</b>
1990 - Converted from a railway traffic bridge to a pedestrian bridge	2007 - Condition Survey and an evaluation for load capacity was completed
2014 / 2015 - Deteriorated timber planks and railing pickets replaced	2008 - Additional steel thickness measurements completed to confirm web thickness
2022 - Deteriorated timber planks replaced and railing installed at east approach	

Field Inspection Information:					
Date of Inspection:	June 29, 2022	Type of Inspection:	<input checked="" type="checkbox"/> Reg. OSIM	<input type="checkbox"/> Enh. OSIM	
Inspected By	Alison Friebel				
Others in Party:	Brian Wood P.Eng.				
Eng. Access Equipment:	None				
Special Access Equipment	None				
Weather	Sun	Temperature	23 °C		
Additional Investigations Required:		Priority		Estimated Cost	
		None	Normal	Urgent	
Material Condition Survey		X			
Detailed Deck Condition Survey:		X			
Non-destructive Delamination Survey of Asphalt-Covered Deck:		X			
Concrete Substructure Condition Survey:		X			
Detailed Coating Condition Survey:		X			
Detailed Timber Investigation:		X			
Post-Tensioned Strand Investigation:		X			
Underwater Investigation			X	<b>\$20,000.00</b>	
Fatigue Investigation		X			
Seismic Investigation		X			
Structure Evaluation:		X			
Monitoring		X			
Deformations, Settlements and Movements:		X			
Crack Widths:		X			
RSS Horizontal movements of face:		X			
RSS Vertical movements of overall structure:		X			
RSS Local movements or deterioration of face elements:		X			
RSS Horizontal movements within overall structure:		X			
RSS Vertical movements within overall structure		X			
RSS Lateral earth pressure at the back of facing elements		X			
Investigation Notes:		<b>Total Cost</b>		<b>\$20,000.00</b>	
Overall Structure Notes:					
Recommended Work on Structure	<input type="checkbox"/> None <input type="checkbox"/> Minor Rehab. <input checked="" type="checkbox"/> Major Rehab. <input type="checkbox"/> Replace				
Timing of Recommended Work	<input type="checkbox"/> Urgent <input type="checkbox"/> 1 to 5 years <input checked="" type="checkbox"/> 6 to 10 years				
Overall Comments:	<b>The bridge is in generally fair to good condition. An underwater investigation is recommended for the piers to confirm concrete condition. Rehabilitation is recommended to complete Span 12 steel repairs, and concrete repairs for the three concrete piers within the waterway.</b>				
Date of Next inspection:	2024				
Overall Bridge Condition					
% Poor in Deck	% Poor in Beams	% Poor in Substructure	% Poor in Barrier	Bridge Condition Index (BCI or BCIp)	
1%	1%	2%	0%	BCIp 98.84	BCI 63.14
Overall Bridge Sufficiency					
Traffic	Economic	Width	Alignment	Bridge Sufficiency Index (BSI)	
0	0	0	0	63.14	

<b>Element Data:</b>						
Element Group:	Decks		Length:	98.8		
Element Name:	Wearing Surface		Width:	3.5		
Location:			Height:	0.1		
Material:	2x10 Timber Planks		Count:	1		
Element Type:			Total Quantity:	340.9		
Environment:	Benign		Inspected	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	sq.m	10.0	325.4	5.0	0.5	

Comments: Boards along center of path have light wear. Light to medium checks typical. Severe split board at west end.

Recommended Work:	Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:	12 - Bridge Surface Repair		
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input checked="" type="checkbox"/>
				Replace 1 split board		

**Element Photo:**




**Description of Photo:** Deck Wearing Surface

**Element Photo:**



**Description of Photo:** Deck Wearing Surface

**Element Photo:**



**Description of Photo:** Deck Wearing Surface




Element Data:						
Element Group:	Decks		Length:	4.4		
Element Name:	Deck Top		Width:	0.25		
Location:			Height:	0.25		
Material:	Timber		Count:	205		
Element Type:	Transverse Cross Ties		Total Quantity:	902.0		
Environment:	Benign		Inspected	Yes <input type="checkbox"/>	No <input type="checkbox"/>	limited <input checked="" type="checkbox"/>
Protection System:	Pressure Treated					Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	sq.m		846.5	46.0	9.5	
Comments: Light weathering typical. Localized light to severe checks and splits typical. Moisture indicated in timbers. Northeast end, one cross ties has severe rot at end of member. Limited inspection due to middle section of timbers covered by timber deck.  Note: 74 timers at east end, 88 at north end, and 43 along centre of bridge.						
Recommended Work:		Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:		
Urgent: <input type="checkbox"/>		1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/> 2 Year: <input type="checkbox"/>

**Element Photo:**



**Description of Photo:** Deck Top

Element Photo:



Description of Photo: Deck Top

Element Photo:



Description of Photo: Deck Top

Element Data:						
Element Group:	Sidewalk/Curb		Length:	98.8		
Element Name:	Curbs		Width:	0.4		
Location:	North and South Side of Deck		Height:	0.125		
Material:	Timber		Count:	2		
Element Type:	4 m long sections		Total Quantity:	207.5		
Environment:	Moderate		Inspected	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	8 - Pedestrian / vehicular hazard
	sq.m	25.4	129.6	38.5	14.0	
Comments: Light to medium weathering, checks and splits, typical. Severe rot, north side 6 timbers and south side 3 timbers.						
Recommended Work:		Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:	9 - Timber Repair	
Urgent: <input type="checkbox"/>		1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input checked="" type="checkbox"/> 2 Year: <input type="checkbox"/>
				Replace rotten timbers		

**Element Photo:**



**Description of Photo:** Curb

Element Photo:



Description of Photo: Curb

Element Photo:



Description of Photo: Curb

<b>Element Data:</b>						
Element Group:	Barriers		Length:	48.0 (Timber), 50.8 (Steel)		
Element Name:	Railing Systems		Width:			
Location:	Length of Bridge		Height:	1.2 (Timber), 2.5 (Steel)		
Material:	Steel and Timber		Count:	2		
Element Type:	Post and Steel Barriers		Total Quantity:	198.0		
Environment:	Benign		Inspected	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	m		197.6	0.2	0.2	

Comments: Timber railing system is in generally good condition. 1 missing timber post at northeast and 1 split timber post at southeast. Isolated areas of light splintering at bolt hole locations. Steel through girder span girders acts as railing system and is in generally good condition with light corrosion, typical. Consider increasing timber barrier height to 1.37 m to meet current code requirements for cyclists, however 1.2m can be used based on owner approval.

Recommended Work:	Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:	3 - Railing System Repair		
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input checked="" type="checkbox"/>	2 Year: <input type="checkbox"/>
				Replace 2 timber posts.		

**Element Photo:**



**Description of Photo:** Railing System

Element Photo:



Description of Photo: Railing System

Element Photo:



Description of Photo: Railing System

**Element Data:**

Element Group:	Beams/Main Longitudinal Elements	Length:	22.6			
Element Name:	Girders	Width:	0.5			
Location:	Span 10 from east	Height:	2.45			
Material:	Steel	Count:	2			
Element Type:	Through Plate Girder	Total Quantity:	311.9			
Environment:	Benign	Inspected	Yes <input type="checkbox"/> No <input type="checkbox"/> limited <input checked="" type="checkbox"/>			
Protection System:						
Condition Data:	Units	Excellent	Good	Fair	Poor*	Performance Deficiencies
	sq.m		263.6	45.2	3.1	

Comments: Light corrosion, typical. Assumed medium corrosion along bottom components, and isolated locations of severe corrosion based on Span 12 steel through plate girder observations.

Recommended Work:	Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:			
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input type="checkbox"/>

**Element Photo:**



**Description of Photo:** Inside Face of Girder

Element Data:						
Element Group:	Beams/Main Longitudinal Elements		Length:	14.3		
Element Name:	Girders		Width:	0.5		
Location:	Span 11 from east		Height:	2.0		
Material:	Steel		Count:	2		
Element Type:	Deck Plate Girders		Total Quantity:	171.6		
Environment:	Benign		Inspected	Yes <input type="checkbox"/>	No <input type="checkbox"/>	limited <input checked="" type="checkbox"/>
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	sq.m		141.3	28.6	1.7	
Comments: Light corrosion, typical. Assumed medium corrosion along bottom components, and isolated locations of severe corrosion based on Span 12 steel through plate girder observations.						
Recommended Work:		Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:		
Urgent: <input type="checkbox"/>		1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>
				2 Year: <input type="checkbox"/>		

**Element Photo:**



**Description of Photo:** Elevation View



**Element Data:**

Element Group:	Beams/Main Longitudinal Elements	Length:	25.5			
Element Name:	Girders	Width:	0.5			
Location:	Span 12 from east	Height:	2.5			
Material:	Steel	Count:	2			
Element Type:	Through Plate Girders	Total Quantity:	357.0			
Environment:	Benign	Inspected	Yes <input type="checkbox"/> No <input type="checkbox"/> limited <input checked="" type="checkbox"/>			
Protection System:						
Condition Data:	Units	Excellent	Good	Fair	Poor*	Performance Deficiencies
	sq.m		297.1	51.0	8.9	

Comments: **Light corrosion typical. Significant areas of the bottoms of stiffeners have medium to very severe corrosion with up to approximately 50% section loss. Several bottoms of stiffeners have very severe corrosion with up to 100% section loss, particularly along the north side.**

Recommended Work:	Rehab: <input checked="" type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:			
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input checked="" type="checkbox"/>	None: <input type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input type="checkbox"/>
Select repairs to structural steel						

**Element Photo:**



Description of Photo: DSCN8335.JPG

Element Photo:



Description of Photo: Exterior Face, Note Corrosion at Bottom of Stiffeners

Element Photo:



Description of Photo: View Towards Abutment

Element Data:						
Element Group:	Beams/Main Longitudinal Elements		Length:	4.6		
Element Name:	Crossties		Width:	0.25		
Location:	Timber Trestle Spans		Height:	0.25		
Material:	Timber		Count:	114		
Element Type:	Cross Tie		Total Quantity:	524.4		
Environment:	Benign		Inspected	Yes <input type="checkbox"/>	No <input type="checkbox"/>	limited <input checked="" type="checkbox"/>
Protection System:	Creosote					Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	sq.m		466.7	52.4	5.2	
Comments: Light weathering typical. Localized light to medium checks and splits, typical. Isolated severe checks and splits.						
Recommended Work:		Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:		
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input type="checkbox"/>

**Element Photo:**



**Description of Photo:** Crossties

Element Photo:



Description of Photo: Cross-ties

Element Photo:



Description of Photo: Cross-ties

Element Data:						
Element Group:	Beams/Main Longitudinal Elements		Length:	4.4		
Element Name:	Floor Beams		Width:	0.3		
Location:	Spans 10 and 12		Height:	0.6		
Material:	Steel		Count:	15		
Element Type:	Through Plate Girders		Total Quantity:	118.8		
Environment:	Benign		Inspected	Yes <input type="checkbox"/>	No <input type="checkbox"/>	limited <input checked="" type="checkbox"/>
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	sq.m		79.2	1.2		

Comments: **Limited inspection due to lack of access. Light corrosion, typical. Assumed isolated areas of medium corrosion.**

Recommended Work:	Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:	
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/> 1 Year: <input type="checkbox"/> 2 Year: <input type="checkbox"/>



**Description of Photo:** Floor Beams

Element Data:						
Element Group:	Beams/Main Longitudinal Elements		Length:	34.1		
Element Name:	Stringers		Width:	0.25		
Location:	Timber Trestle Spans		Height:	0.4		
Material:	Timber		Count:	8		
Element Type:			Total Quantity:	354.6		
Environment:	Benign		Inspected	Yes <input type="checkbox"/>	No <input type="checkbox"/>	limited <input checked="" type="checkbox"/>
Protection System:	Creosote					Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	each		333.4	17.7	3.5	

Comments: **Light weathering, typical. Light to medium checks and splits, typical. Isolated severe checks and splits.**

Recommended Work:	Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>
			Urgent: <input type="checkbox"/>
			1 Year: <input type="checkbox"/>
			2 Year: <input type="checkbox"/>

**Element Photo:**



**Description of Photo:** Stringers

Element Photo:



Description of Photo: Stringers

Element Photo:



Description of Photo: Stringers

Element Data:						
Element Group:	Bracing		Length:	5.9		
Element Name:	Bracing		Width:	0.8		
Location:	Timber Trestle Spans		Height:	0.25		
Material:	Timber		Count:	18		
Element Type:			Total Quantity:	106.2		
Environment:	Benign		Inspected	Yes <input type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>
Protection System:	Creosote					Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	m		99.8	5.3	1.1	

Comments: Localized light to severe checks and splits, typical. One brace near first east pier has severe rot at the end of the member.

Recommended Work:	Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:	9 - Timber Repair
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/> 1 Year: <input type="checkbox"/> 2 Year: <input checked="" type="checkbox"/>
				Replace damaged brace

**Element Photo:**



Description of Photo: Bracing



<b>Element Data:</b>						
Element Group:	Coating		Length:			
Element Name:	Structural Steel		Width:			
Location:			Height:			
Material:	Paint		Count:			
Element Type:			Total Quantity:	840.5		
Environment:	Benign		Inspected	Yes <input type="checkbox"/>	No <input type="checkbox"/>	limited <input checked="" type="checkbox"/>
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	sq.m		168.1	168.1	504.3	

Comments: The two Through Plate Girder spans, interior faces, were painted by the Rotary Club in 2005 and the paint is in generally good condition. The remaining coatings are generally in poor condition with some fair, in combination with Category 2 and 3 rust conditions, and isolated Category 4 rust conditions.

Recommended Work:	Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:	
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/> 1 Year: <input type="checkbox"/> 2 Year: <input type="checkbox"/>

**Element Photo:**



Description of Photo: Coating

Element Photo:



Description of Photo: Coating

Element Photo:



Description of Photo: Coating

Element Data:						
Element Group:	Abutments		Length:	6.4		
Element Name:	Abutment Walls		Width:			
Location:	East Abutment		Height:	1.6		
Material:	Timber		Count:	1		
Element Type:			Total Quantity:	10.2		
Environment:	Benign		Inspected	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>
Protection System:	Pressure Treated					Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	sq.m	9.7	0.5			

Comments: Recently replaced. Isolated areas of light checks.

Recommended Work:	Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:	
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/> 1 Year: <input type="checkbox"/> 2 Year: <input type="checkbox"/>

**Element Photo:**



**Description of Photo:** East Abutment

Element Data:						
Element Group:	Abutments		Length:	5.0		
Element Name:	Abutment Walls		Width:			
Location:	West Abutment		Height:	1.2		
Material:	Concrete		Count:	1		
Element Type:	Cast-in-Place		Total Quantity:	6.0		
Environment:	Benign		Inspected	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	sq.m		2.7	2.0	1.3	

Comments: Light scaling, typical. Evidence of wet areas with efflorescence and localized light to severe disintegration around edges. Some spalls have wet areas and efflorescence. Very severe 1,000x250x75 mm disintegration. Severe 1,500x600x25 deep scaling and disintegration. Two very severe 1,500x50x25 mm deep spalls. Medium 200x250x25 mm spall. Ballast wall behind end diaphragm not inspected.

Recommended Work:	Rehab: <input checked="" type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:	
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input checked="" type="checkbox"/>	None: <input type="checkbox"/>	Urgent: <input type="checkbox"/> 1 Year: <input type="checkbox"/> 2 Year: <input type="checkbox"/>

Repair concrete

**Element Photo:**



Description of Photo: West Abutment

Element Photo:



Description of Photo: West Abutment

Element Photo:



Description of Photo: West Abutment

Element Data:						
Element Group:	Abutments		Length:	2.4		
Element Name:	Wingwalls		Width:			
Location:	West Abutment, South Side		Height:	1.2		
Material:	Concrete		Count:	2		
Element Type:	Cast-in-Place		Total Quantity:	5.8		
Environment:	Benign		Inspected	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	sq.m		5.2	0.5	0.1	
Comments: Light scaling, typical. Isolated medium scaling. Medium 150x150x30mm deep spall and four medium 250x50x15mm deep spalls. Some efflorescence at the connection to the abutment.						
Recommended Work:		Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:		
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input type="checkbox"/>

**Element Photo:**



**Description of Photo:** Wingwall

<b>Element Data:</b>						
Element Group:	Abutments		Length:			
Element Name:	Bearings		Width:			
Location:	West Abutment		Height:			
Material:	Steel		Count:	2		
Element Type:			Total Quantity:	2		
Environment:	Benign		Inspected	Yes <input type="checkbox"/>	No <input type="checkbox"/>	limited <input checked="" type="checkbox"/>
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	each			2		

Comments: Bearings have medium corrosion with debris accumulating around the bearings.

Recommended Work:	Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:	2 - Bridge Cleaning		
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input checked="" type="checkbox"/>	2 Year: <input type="checkbox"/>
				Clean debris from bearing seat.		

**Element Photo:**



Description of Photo: Bearings

Element Photo:



Description of Photo:      Bearings

Element Photo:

Description of Photo:



Element Data:						
Element Group:	Piers		Length:			
Element Name:	Shafts/Columns/Pile Bents		Width:	0.3 dia.		
Location:	East Abutment		Height:	0.6		
Material:	Timber		Count:	6		
Element Type:			Total Quantity:	3.4		
Environment:	Benign		Inspected	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>
Protection System:	Creosote					Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	sq.m		3.4			

Comments: Light weathering typical. Localized light checks and splits.

Recommended Work:	Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:	
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/> 1 Year: <input type="checkbox"/> 2 Year: <input type="checkbox"/>

**Element Photo:**



Description of Photo: Piles

Element Data:						
Element Group:	Piers		Length:			
Element Name:	Shafts/Columns/Pile Bents		Width:	0.3 dia.		
Location:	Timber Trestle Spans		Height:	3.0		
Material:	Timber		Count:	36		
Element Type:			Total Quantity:	102.0		
Environment:	Benign		Inspected	Yes <input type="checkbox"/>	No <input type="checkbox"/>	limited <input checked="" type="checkbox"/>
Protection System:	Creosote					Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	sq.m		95.9	5.1	1.0	

Comments: Light weathering, typical. Localized light to severe medium checks and splits, typical.

Recommended Work:	Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:	
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/> 1 Year: <input type="checkbox"/> 2 Year: <input type="checkbox"/>

**Element Photo:**



Description of Photo: Piles

Element Data:						
Element Group:	Piers		Length:	5.0		
Element Name:	Shafts/Columns/Pile Bents		Width:	3.5		
Location:	Spans 10, 11, and 12		Height:	4.8		
Material:	Concrete		Count:	3		
Element Type:	Cast-in-Place		Total Quantity:	297.3		
Environment:	Benign		Inspected	Yes <input type="checkbox"/>	No <input type="checkbox"/>	limited <input checked="" type="checkbox"/>
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	sq.m		174.9	61.2	61.2	
Comments: Limited inspection due to lack of access. Light to very severe scaling and large areas of light to severe disintegration. East pier has localized exposed rebar. Narrow to medium cracking with staining and efflorescence noted at all piers. Areas of light to severe erosion at base of all piers at waterline.						
Recommended Work:		Rehab: <input checked="" type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:		
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input checked="" type="checkbox"/>	None: <input type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input type="checkbox"/>
Abutments originally designed for railway loading - deterioration not anticipated to impact load carrying capacity at this time. Future repairs should be planned for.						

**Element Photo:**



**Description of Photo:** West Pier West Face

Element Photo:



Description of Photo: West Pier East Face

Element Photo:



Description of Photo: Centre Pier East Face

Element Data:						
Element Group:	Piers	Length:	4.3			
Element Name:	Caps	Width:	0.3			
Location:	East Abutment	Height:	0.3			
Material:	Timber	Count:	1			
Element Type:		Total Quantity:	5.2			
Environment:	Benign	Inspected	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>	
Protection System:	Creosote					Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	sq.m		5.2			

Comments: Light weathering, typical. Localized light checks and splits.

Recommended Work:	Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:	
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/> 1 Year: <input type="checkbox"/> 2 Year: <input type="checkbox"/>

**Element Photo:**



Description of Photo: Pile Cap

Element Data:						
Element Group:	Piers	Length:	5.0			
Element Name:	Caps	Width:	0.35			
Location:	Timber Trestle Spans	Height:	0.35			
Material:	Timber	Count:	6			
Element Type:		Total Quantity:	42.0			
Environment:	Benign	Inspected	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>	
Protection System:	Creosote					Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	sq.m		37.4	4.2	0.4	
Comments: Light weathering, typical. Localized light to severe medium checks and splits.						
Recommended Work:		Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:		
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input type="checkbox"/>

**Element Photo:**



**Description of Photo:** Pile Cap


Element Data:						
Element Group:	Piers		Length:			
Element Name:	Bearings		Width:			
Location:			Height:			
Material:	Steel		Count:	12		
Element Type:			Total Quantity:	12		
Environment:	Benign		Inspected	Yes <input type="checkbox"/>	No <input type="checkbox"/>	limited <input checked="" type="checkbox"/>
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	each		6	6		
Comments: <b>Limited inspection due to height restriction. Deck Plate Girder span, bearings appear to have medium corrosion at east end. Remaining bearings assumed to be in good to fair condition as a result of corrosion.</b>						
Recommended Work:		Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:		
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input type="checkbox"/>

**Element Photo:**



**Description of Photo:** Pier Bearings

Element Photo:



Description of Photo: Pier Bearings

Element Photo:



Description of Photo: Pier Bearings



<b>Element Data:</b>						
Element Group:	Retaining Walls		Length:	40.0		
Element Name:	Walls		Width:			
Location:	Southwest		Height:	1.2		
Material:	Concrete		Count:	2		
Element Type:	Cast-in-Place		Total Quantity:	96.0		
Environment:	Benign		Inspected	Yes <input type="checkbox"/>	No <input type="checkbox"/>	limited <input checked="" type="checkbox"/>
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	sq.m		96.0			

Comments: **Light scaling, typical.**

Recommended Work:	Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:			
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input type="checkbox"/>

**Element Photo:**




**Description of Photo:** Retaining Wall

<b>Element Data:</b>						
Element Group:	Retaining Walls		Length:	40.0		
Element Name:	Railing System on Walls		Width:			
Location:	Southwest		Height:	1.1		
Material:	Timber		Count:	2		
Element Type:			Total Quantity:	80.0		
Environment:	Benign		Inspected	Yes <input type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	m		50.0	20.0	10.0	

Comments: Light weathering, typical. 18 broken post or missing posts. 3.0m of top rail is missing. Several post anchors have become unattached.

Recommended Work:	Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:	3 - Railing System Repair		
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input checked="" type="checkbox"/>
				Replace missing and broken pickets, anchors and top rail.		

**Element Photo:**



**Description of Photo:** Railing System

**Element Photo:**



**Description of Photo:** Railing System

**Element Photo:**



**Description of Photo:** Railing System

<b>Element Data:</b>						
Element Group:	Embankments & Streams		Length:			
Element Name:	Streams and Waterways		Width:			
Location:	North and South		Height:			
Material:			Count:			
Element Type:			Total Quantity:	1		
Environment:	Benign		Inspected	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	all	X				

Comments: **Armour around east end barriers. Waterway is free flowing. No observed defects.**

Recommended Work:	Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:			
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input type="checkbox"/>

**Element Photo:**



**Description of Photo:** Waterway Looking Upstream

**Element Photo:**



**Description of Photo:** Waterway Looking Downstream

**Element Photo:**



**Description of Photo:** Waterway Looking Upstream

<b>Element Data:</b>						
Element Group:	Embankments & Streams		Length:			
Element Name:	Embankments		Width:			
Location:	All Quadrants		Height:			
Material:	Trees, Shrubs and Earth		Count:	4		
Element Type:	Vegetation		Total Quantity:	4		
Environment:	Benign		Inspected	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	each	4				

Comments: **No observed defects. Embankments are vegetated and appear stable.**


Recommended Work:	Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:			
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input type="checkbox"/>

**Element Photo:**




**Description of Photo:** Embankment

Element Photo:



Description of Photo: Embankment

Element Photo:



Description of Photo: Embankment

Element Data:						
Element Group:	Accessories		Length:			
Element Name:	Signs		Width:			
Location:	East End		Height:			
Material:			Count:	3		
Element Type:			Total Quantity:	3		
Environment:	Benign		Inspected	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	each		2	1		
Comments: One caution sign in poor condition and has been damaged, bent and is weathered. One stop sign ahead sign has graffiti.						
Recommended Work:		Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:		
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input type="checkbox"/>

**Element Photo:**



**Description of Photo:** Signs



<b>Element Data:</b>						
Element Group:	Accessories		Length:			
Element Name:	Utilities		Width:			
Location:	Along Bridge		Height:			
Material:	Steel Light Posts		Count:	4		
Element Type:	Lighting		Total Quantity:	4		
Environment:	Benign		Inspected	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>
Protection System:	Paint					Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	each		4			

Comments: Posts are in good condition. One light stand missing bottom housing.

Recommended Work:	Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:			
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input type="checkbox"/>

**Element Photo:**



**Description of Photo:** Light Utility

<b>Element Data:</b>						
Element Group:	Accessories		Length:			
Element Name:	Other		Width:			
Location:	Length of Structure		Height:			
Material:	PVC		Count:	1		
Element Type:	Electrical		Total Quantity:	1		
Environment:	Benign		Inspected	Yes <input type="checkbox"/>	No <input type="checkbox"/>	limited <input checked="" type="checkbox"/>
Protection System:	Conduit					Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	each	1				

Comments: **Conduit repaired from previous inspection. No observed defects.**

Recommended Work:	Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:			
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input type="checkbox"/>

**Element Photo:**



**Description of Photo:** Electrical Utilities

<b>Element Data:</b>						
Element Group:	Approaches		Length:	6.0		
Element Name:	Wearing Surface		Width:	3.0		
Location:	West and East End		Height:			
Material:	Gravel		Count:	2		
Element Type:			Total Quantity:	36.0		
Environment:	Benign		Inspected	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	sq.m		36.0			

Comments: **Light wear typical. No other observed defects.**

Recommended Work:	Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:	
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/> 1 Year: <input type="checkbox"/> 2 Year: <input type="checkbox"/>

**Element Photo:**



**Description of Photo:** Approach Surface

Element Data:						
Element Group:	Approaches		Length:	3.65		
Element Name:	Barrier		Width:			
Location:	East End		Height:	1.1(SW), 1.3 (SE)		
Material:	Timber		Count:	2		
Element Type:			Total Quantity:	7.3		
Environment:	Benign		Inspected	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>
Protection System:	Pressure Treated					Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	m	6.6	0.7			

Comments: One 3.0m light check at southeast top timber. No other observed defects.

Recommended Work:	Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:	
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/> 1 Year: <input type="checkbox"/> 2 Year: <input type="checkbox"/>

**Element Photo:**



Description of Photo: Approach Barrier

Repair and Rehabilitation Required:		Priority				Estimated Structural Cost
Element <sup>1</sup>	Repair and Rehabilitation Required <sup>2</sup>	6 to 10 Years	1 to 5 Years	Within 1 Year	Urgent	
Structure	Demolition					
Structure	Replacement					
OR						
Deck	Rehab. =					
Sidewalk/Curb	Rehab. =					
Barrier	Rehab. =					
Joints	Rehab. =					
Beams	Rehab. = Repair steel	X				\$80,000.00
Abutment	Rehab. = Repair Concrete	X				\$15,000.00
Pier	Rehab. = Repair Concrete	X				\$600,000.00
Wingwalls	Rehab. =					
Retaining Wall	Rehab. =					
Estimated Rehabilitated or Replacement Structure Dimensions <sup>3</sup>						
Total Deck Length (m)   Overall Str. Width (m)		Total Structural Cost				\$695,000.00

1 - Indicate specific costs for structure replacement OR for rehabilitation under the given headings.

2 - Give a very brief description of the rehabilitation work required.

3 - Estimated structure dimensions after completion of the proposed work - if it is expected to change.

Associated Work	Comments	Estimated Associated Work Cost
Approaches		
Detours	Trail Closure Signage	\$2,000.00
Traffic Control		
Utilities		
Other	Engineering and Contingency	\$100,000.00
	Mobilization / Demobilization, General, Insurance	\$100,000.00
	Access / Dewatering / Environmental	\$150,000.00
Total Associated Work Cost		\$352,000.00
Total Construction Cost		\$1,047,000.00

**Justification:**

The most westerly Span 12 Through Plate Girder has several vertical stiffeners with 100% section loss at the interface with the bottom flange, and there is isolated severe corrosion and section loss on other members generally towards the abutment, however load carrying capacity is not a concern at this time. The three concrete piers supporting Spans 10, 11 and 12 have severe concrete deterioration along the waterline. Rehabilitation is recommended to include Span 12 steel repairs and concrete repairs for the three piers. For maintenance, timber member replacements will be ongoing, and the west abutment bearings should be cleaned to remove debris and other deleterious material. Note that the barrier height could be considered to be increased to 1.37 m to meet current code requirements for cyclists, however 1.2 m can be used based on owner approval.

**Inventory Data:**

Structure Name	<b>Seguin Street Bridge</b>		
Main Highway #	<b>Seguin Street</b>	On <input checked="" type="checkbox"/> or Under <input type="checkbox"/> Structure	Service on Structure <input type="checkbox"/> Navig. Water <input type="checkbox"/> Non-Navig. Water <input type="checkbox"/> Rail <input checked="" type="checkbox"/> Road <input checked="" type="checkbox"/> Ped. <input type="checkbox"/> Other
Location Description	0.08km West of River Street	Service under:	<input checked="" type="checkbox"/> Navig. Water <input type="checkbox"/> Non-Navig. Water <input type="checkbox"/> Rail <input type="checkbox"/> Road <input type="checkbox"/> Ped. <input type="checkbox"/> Other
Owner/Custodian	Town of Parry Sound		
MTO Region	Northeastern	Latitude	45° 20' 37" N Longitude 80° 01' 52" W
Regional Engineer		Heritage Designation:	<input checked="" type="checkbox"/> Not Cons. <input type="checkbox"/> Cons./Not App. <input type="checkbox"/> List/Not Desig. Desig. <input type="checkbox"/> Desig./Not List <input type="checkbox"/> Desig. & List
MTO Area	<b>52 - Huntsville</b>	Hwy Class:	Freeway <input type="checkbox"/> Arterial <input checked="" type="checkbox"/> Collector <input type="checkbox"/> Local <input type="checkbox"/>
Old County	<b>44 - Parry Sound</b>	Posted Speed	<b>50</b> No. of Lanes <b>4</b>
Township	<b>452 McDougall</b>	AADT	<b>Unknown</b> % Truck <b>Unknown</b>
Structure Type 1	<b>Trapezoidal Box Beam Girders</b>		
Structure Material 1	<b>Weathering Steel</b>	Traffic Directional Bound	<b>W-E</b>
Structure Type 2	<b>Concrete Deck</b>		
Structure Material 2	<b>Cast-in-Place Concrete</b>		
Total Deck Length	<b>55.9</b> (m)	Inspection Frequency	<b>2</b> (years)
Overall Str. Width	<b>20.6</b> (m)	Inspection Year	<b>2022</b>
Culvert Length	<b>0</b> (m)	Inspection Duration	<b>3</b> (hrs)
Total Deck Area	<b>1151.54</b> (sq.m)	Min. Vertical Clearance	<input type="text"/> (m)
Roadway Width	<b>15.0</b> (m)	Detour Distance	<b>2.2</b> (km)
Skew Angle	<b>0</b> (Degree)	Fill on Structure	<b>0</b> (m)
No. of Spans	<b>1</b>	Span Lengths	<b>55.0</b> (m)
<u>For retaining wall:</u>			
Total Wall Length	<input type="text"/> (m)	Max. Wall Height	<input type="text"/> (m)
Total Wall Area	<input type="text"/> (sq.m)	Ave. Wall Height	<input type="text"/> (m)
		Angle of Backfill	<input type="text"/> (Degrees)

**Historical Data**

Year Built	<b>1987</b>	Year of superstruct. Constructed	<b>1987</b>
Last Reg. OSIM Inspection	<b>2020</b>	Year of Last Minor Rehab.	<b>N/A</b>
Last Enh. OSIM Inspection	<input type="text"/>	Year of Last Major Rehab	<b>N/A</b>
		Current Load Limit	<input type="text"/> / <input type="text"/> / <input type="text"/> (tonnes)

<u>Work History: (Date/description)</u>	<u>Investigation History: (Date/description)</u>
	2007 - Steel thickness measurements were completed and an evaluation for load capacity was completed

Field Inspection Information:					
Date of Inspection:	June 29, 2022	Type of Inspection:	<input type="checkbox"/> Reg. OSIM	<input type="checkbox"/> Enh. OSIM	
Inspected By	Alison Friebel				
Others in Party:	Brian Wood P.Eng, Bill Glover Rescue Technician from Safety Design Systems				
Eng. Access Equipment:	Tape measure and Camera				
Special Access Equipment	Access ladder, Air monitor, Flashlight, Restraining harness, Retrieval system				
Weather	Sun and Cloud	Temperature	20 °C		
Additional Investigations Required:			Priority		Estimated Cost
			None	Normal	
Material Condition Survey			X		
Detailed Deck Condition Survey:			X		
Non-destructive Delamination Survey of Asphalt-Covered Deck:			X		
Concrete Substructure Condition Survey:			X		
Detailed Coating Condition Survey:			X		
Detailed Timber Investigation:			X		
Post-Tensioned Strand Investigation:			X		
Underwater / Boat Access Investigation				X	\$20,000.00
Fatigue Investigation			X		
Seismic Investigation			X		
Structure Evaluation:			X		
Monitoring			X		
Deformations, Settlements and Movements:			X		
Crack Widths:			X		
RSS Horizontal movements of face:			X		
RSS Vertical movements of overall structure:			X		
RSS Local movements or deterioration of face elements:			X		
RSS Horizontal movements within overall structure:			X		
RSS Vertical movements within overall structure			X		
RSS Lateral earth pressure at the back of facing elements			X		
Investigation Notes:	"Underwater/Boat Access Investigation" refers to using a Bridgmaster to inspect outside faces of box girders, and		<b>Total Cost</b>		<b>\$20,000.00</b>
Overall Structure Notes:					
Recommended Work on Structure	<input type="checkbox"/> None <input checked="" type="checkbox"/> Minor Rehab. <input type="checkbox"/> Major Rehab. <input type="checkbox"/> Replace				
Timing of Recommended Work	<input type="checkbox"/> Urgent <input checked="" type="checkbox"/> 1 to 5 years <input type="checkbox"/> 6 to 10 years				
Overall Comments:	<b>Bridge is in generally good condition. Rehabilitation is recommended to clean inside of girder ends and apply a new coating, repair sidewalk concrete, and upgrade approach guide rail to bridge connections. Built in 1987, a Bridgmaster inspection of the exterior of the girders should be undertaken, it is unknown when if any previous Bridgmaster inspection was conducted.</b>				
Date of Next inspection:	2024				
Overall Bridge Condition					
% Poor in Deck	% Poor in Beams	% Poor in Substructure	% Poor in Barrier	Bridge Condition Index (BCI or BCIp)	
0%	0%	0%	0%	BCIp 99.87	BCI 81.72
Overall Bridge Sufficiency					
Traffic	Economic	Width	Alignment	Bridge Sufficiency Index (BSI)	
0	5	0	0	76.72	

Element Data:						
Element Group:	Decks		Length:	55.9		
Element Name:	Wearing Surface		Width:	15.0		
Location:			Height:	0.1		
Material:	Asphalt		Count:	1		
Element Type:			Total Quantity:	838.5		
Environment:	Severe		Inspected	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	sq.m		726.7	111.8		

Comments: Light ravelling, typical. Center 2 lanes have medium wheel rutting full length of bridge (55.9m x 0.5m x 4).

Recommended Work:	Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:	
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/> 1 Year: <input type="checkbox"/> 2 Year: <input type="checkbox"/>

**Element Photo:**




**Description of Photo:** Wearing Surface



Element Data:						
Element Group:	Decks		Length:	55.9		
Element Name:	Deck Top (with Thin Slab)		Width:	20.6		
Location:			Height:	0.25		
Material:	Concrete		Count:	1		
Element Type:	Cast-in-Place		Total Quantity:	1151.5		
Environment:	Moderate		Inspected	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>	limited <input type="checkbox"/>
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	sq.m		1151.5			

Comments: **Assumed to be in good condition based on asphalt.**

Recommended Work:	Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:	
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/> 1 Year: <input type="checkbox"/> 2 Year: <input type="checkbox"/>



**Description of Photo:** Deck Top

Element Data:						
Element Group:	Decks		Length:	55.9		
Element Name:	Soffit - Thin Slab		Width:	14.0		
Location:	Exterior Soffit		Height:			
Material:	Concrete		Count:	1		
Element Type:	Cast-in-Place		Total Quantity:	782.6		
Environment:	Benign		Inspected	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	sq.m		772.6	8.0	2.0	

Comments: Light scaling typical. Narrow to medium cracks with some water staining along overhang soffit at regular intervals (+/- 2.0m c/c avg.). Several cracks with wet areas and leachate deposits.

Recommended Work:	Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:	
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/> 1 Year: <input type="checkbox"/> 2 Year: <input type="checkbox"/>

**Element Photo:**



**Description of Photo:** Exterior Soffit

Element Photo:



Description of Photo: Exterior Soffit

Element Photo:



Description of Photo: Interior Soffit

Element Data:						
Element Group:	Decks		Length:	55.9		
Element Name:	Soffit - Inside Boxes		Width:	2.2		
Location:	Inside Boxes		Height:			
Material:	Concrete		Count:	3		
Element Type:	Cast-in-Place		Total Quantity:	368.9		
Environment:	Benign		Inspected	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	sq.m		363.9	4.0	1.0	

Comments: Light scaling, typical. North girder soffit has 4.0 m of narrow to medium cracks with efflorescence. South girder soffit has isolated areas of efflorescence built up at slab and girder top flange interface, and one 0.5 m crack with efflorescence. Remainder of soffit areas have several narrow to medium transverse cracks.

Recommended Work:	Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>
			Urgent: <input type="checkbox"/>
			1 Year: <input type="checkbox"/>
			2 Year: <input type="checkbox"/>

**Element Photo:**



**Description of Photo:** North Girder Interior Soffit

Element Photo:



Description of Photo: South Girder Interior Soffit

Element Photo:



Description of Photo: South Girder Interior Soffit

<b>Element Data:</b>						
Element Group:	Decks		Length:	0.5		
Element Name:	Drainage System		Width:	0.2		
Location:	Along face of sidewalks		Height:			
Material:	Steel		Count:	8		
Element Type:	Metal Drain Pipes		Total Quantity:	8		
Environment:	Severe		Inspected	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>
Protection System:	Hot Dip galvanizing					Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	each		8			

Comments: Light corrosion at bottom of drain pipes, typical. No other observed defects. No debris buildup in drain grates.

Recommended Work:	Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:	
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/> 1 Year: <input type="checkbox"/> 2 Year: <input type="checkbox"/>

**Element Photo:**



**Description of Photo:** Drainage

<b>Element Data:</b>						
Element Group:	Joints		Length:	20.6		
Element Name:	Seals/sealants		Width:			
Location:	East and West		Height:			
Material:	Neoprene		Count:	2		
Element Type:	Strip Seal		Total Quantity:	2		
Environment:	Severe		Inspected	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	each		2			

Comments: Seals are in generally good condition. No evidence of leakage or other performance deficiencies.

Recommended Work:	Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:	2 - Bridge Cleaning		
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input checked="" type="checkbox"/>	2 Year: <input type="checkbox"/>
				Clean joint gap and seals yearly.		

**Element Photo:**



**Description of Photo:** Joint Seals

Element Data:						
Element Group:	Joints		Length:	15.0		
Element Name:	Concrete End Dams		Width:	0.5		
Location:	East and West		Height:			
Material:	Concrete		Count:	4		
Element Type:			Total Quantity:	30.0		
Environment:	Severe		Inspected	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	sq.m		30.0			

Comments: Light scaling and abrasions typical. Light 300 x100 x15mm spall on east side and 2 light 300x100x15mm spall on west side. Approximately 1.0m of light cracks.

Recommended Work:	Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:	
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/> 1 Year: <input type="checkbox"/> 2 Year: <input type="checkbox"/>

**Element Photo:**



**Description of Photo:** Joint Concrete End Dam



**Element Photo:**



**Description of Photo:** Joint Concrete End Dam

**Element Photo:**

**Description of Photo:**

<b>Element Data:</b>						
Element Group:	Joints		Length:	20.6		
Element Name:	Armouring/Retaining Devices		Width:			
Location:	East and West		Height:			
Material:	Steel		Count:	8		
Element Type:	Angle		Total Quantity:	164.8		
Environment:	Severe		Inspected	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	m		160.8	4.0		

Comments: **Light corrosion typical. Isolated deformations within wheel lines, typical.**

Recommended Work:	Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:	
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/> 1 Year: <input type="checkbox"/> 2 Year: <input type="checkbox"/>

**Element Photo:**



**Description of Photo:** Joint Armour

Element Data:						
Element Group:	Sidewalk/Curb		Length:	55.9		
Element Name:	Sidewalks and Medians		Width:	2.8		
Location:	North and South		Height:	0.25		
Material:	Concrete		Count:	2		
Element Type:	Sidewalk		Total Quantity:	313.0		
Environment:	Severe		Inspected	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	8 - Pedestrian / vehicular hazard
	sq.m		307.7	3.1	2.2	

Comments: Light scaling, typical. Wear and abrasions along top edges, typical. North sidewalk has 11 - 2.0 m narrow to medium cracks, 2 - 1.5m narrow cracks and 1 light spall. South sidewalk has 13 - 2.0m light to medium cracks, severe 2.0x0.6 m spall with rebar exposed rebar, 300x300x25mm medium spall at east end, and 3-500x100mm light spalls. One 1.0x1.0m area of delamination.

Recommended Work:	Rehab: <input checked="" type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:			
Urgent: <input type="checkbox"/>	1-5 Years: <input checked="" type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input type="checkbox"/>
Repair spalls and delamination area.						

Element Photo:




Description of Photo: Sidewalk Concrete Spall and Delamination

Element Photo:



Description of Photo: Sidewalk Concrete Delamination

Element Photo:



Description of Photo: Sidewalk Concrete Delamination

<b>Element Data:</b>						
Element Group:	Barriers		Length:	72.0		
Element Name:	Railing Systems		Width:			
Location:	North and South		Height:			
Material:	Aluminum		Count:	2		
Element Type:	4 Rail Metal Railing		Total Quantity:	144.0		
Environment:	Severe		Inspected	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	m		135.8	8.0	0.2	

Comments: Two 100x100mm deformations with perforations on north rail. Localized abrasions throughout with some wear of aluminum surface.

Recommended Work:	Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:	
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/> 1 Year: <input type="checkbox"/> 2 Year: <input type="checkbox"/>

**Element Photo:**



**Description of Photo:** Railing System

**Element Photo:**



**Description of Photo:** Railing System

**Element Photo:**



**Description of Photo:** Railing System

Element Data:						
Element Group:	Beams/Main Longitudinal Elements		Length:	2		
Element Name:	Girders Exterior		Width:	2.2		
Location:	Ends		Height:	2.8		
Material:	Steel		Count:	6		
Element Type:	Trapezoidal Box		Total Quantity:	93.6		
Environment:	Moderate		Inspected	Yes <input type="checkbox"/>	No <input type="checkbox"/>	limited <input checked="" type="checkbox"/>
Protection System:	Weathering Steel with Epoxymastic Coating					Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	sq.m		93.0	0.6		

Comments: Five 200x200mm areas of medium corrosion at the bottom flange at drain holes. Light corrosion at top of southwest girder.

Recommended Work:	Rehab: <input checked="" type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:	
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input checked="" type="checkbox"/>	None: <input type="checkbox"/>	Urgent: <input type="checkbox"/> 1 Year: <input type="checkbox"/> 2 Year: <input type="checkbox"/>
Clean and recoat in conjunction with interior cleaning. Refer to Beams - Inside Boxes regarding cleaning.				

**Element Photo:**



**Description of Photo:** Girder - Exterior End

Element Photo:



Description of Photo: Girder - Exterior End

Element Photo:



Description of Photo: Girder - Exterior End



Element Data:						
Element Group:	Beams/Main Longitudinal Elements		Length:	52.7		
Element Name:	Girders Exterior		Width:	2.2		
Location:	Middle		Height:	2.8		
Material:	Steel		Count:	3		
Element Type:	Trapezoidal Box		Total Quantity:	1233.2		
Environment:	Benign		Inspected	Yes <input type="checkbox"/>	No <input type="checkbox"/>	limited <input checked="" type="checkbox"/>
Protection System:	Weathering Steel					Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	sq.m	1233.2				
Comments: No observed defects. Patina is formed and uniform. Limited access, observations from embankments.						
Recommended Work:		Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:		
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input type="checkbox"/>

**Element Photo:**



**Description of Photo:** Girders - Exterior Middle

Element Data:						
Element Group:	Beams/Main Longitudinal Elements		Length:	55.9		
Element Name:	Inside boxes		Width:	2.2		
Location:	North Girder		Height:	2.8		
Material:	Steel		Count:	1		
Element Type:	Trapezoidal Box		Total Quantity:	436.0		
Environment:	Benign		Inspected	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>
Protection System:	Weathering Steel with Epoxymastic Coating at Ends					Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	sq.m	414.0	12.0	7.0	3.0	

Comments: Medium corrosion along bottom, 8.0mx200mm at west and east end of girder. The coating along the bottom flange and stiffeners has failed exhibiting Category 2 to 4 surface rust at west end. 1 sq.m of white deposits on bottom. Steel stiffeners have areas of localized severe corrosion with section loss at ends of girder. 20m from west end 4.0m of efflorescence deposits at top flange and deck interface. Both ends have significant build-up of debris.

Recommended Work:	Rehab: <input checked="" type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:	
Urgent: <input type="checkbox"/>	1-5 Years: <input checked="" type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input type="checkbox"/>	Urgent: <input type="checkbox"/> 1 Year: <input type="checkbox"/> 2 Year: <input type="checkbox"/>
Clean debris from girder ends, recoat the girder ends.				

**Element Photo:**



**Description of Photo:** East Girder End

Element Photo:



Description of Photo: North Girder

Element Photo:



Description of Photo: West Girder End

Element Data:						
Element Group:	Beams/Main Longitudinal Elements		Length:	55.9		
Element Name:	Inside boxes		Width:	2.2		
Location:	Center Girder		Height:	2.8		
Material:	Steel		Count:	1		
Element Type:	Trapezoidal Box		Total Quantity:	436.0		
Environment:	Benign		Inspected	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>
Protection System:	Weathering Steel with Epoxymastic Coating at Ends					Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	sq.m	434.0	2.0			

Comments: 8.0mx100mm of light corrosion along bottom flange at east end of girder. One area of white deposits on the bottom flange. Both ends have some build-up of debris.

Recommended Work:	Rehab: <input checked="" type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:	
Urgent: <input type="checkbox"/>	1-5 Years: <input checked="" type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input type="checkbox"/>	Urgent: <input type="checkbox"/> 1 Year: <input type="checkbox"/> 2 Year: <input type="checkbox"/>
Clean debris from girder ends, recoat the girder ends.				

**Element Photo:**



**Description of Photo:** Center Girder West End

Element Photo:



Description of Photo: Center Girder East End

Element Photo:



Description of Photo: Center Girder

<b>Element Data:</b>						
Element Group:	Beams/Main Longitudinal Elements		Length:	55.9		
Element Name:	Inside boxes		Width:	2.2		
Location:	South Girder		Height:	2.8		
Material:	Steel		Count:	1		
Element Type:	Trapezoidal Box		Total Quantity:	436.0		
Environment:	Benign		Inspected	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>
Protection System:	Weathering Steel with Epoxymastic Coating at Ends					Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	sq.m	408.0	15.0	10.0	3.0	

Comments: Light to medium corrosion along bottom, 15.0mx200mm at west and 6.0mx100mm at east end of girder. The coating along the bottom flange and stiffeners has failed exhibiting Category 2 to 4 surface rust at west end. One section of girder has light corrosion (4.0x2.2m) on bottom. Steel stiffeners have areas of localized severe corrosion with section loss at ends of girder. 20m from west end 4.0m of efflorescence at top flange and deck interface. Isolated areas of efflorescence deposits with corrosion on webs and top flange. Both ends have significant build-up of debris.

Recommended Work:	Rehab: <input checked="" type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:
Urgent: <input type="checkbox"/>	1-5 Years: <input checked="" type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>
Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input type="checkbox"/>	

Clean debris from girder ends, recoat the girder ends.

**Element Photo:**



**Description of Photo:** Girder West End

Element Photo:



Description of Photo: South Girder

Element Photo:



Description of Photo: South Girder

Element Photo:



Description of Photo: South Girder

Element Photo:



Description of Photo: South Girder



Element Data:						
Element Group:	Beams/Main Longitudinal Elements		Length:	6.8		
Element Name:	Diaphragms (steel, wood, etc.)		Width:			
Location:	End		Height:	2.4		
Material:	Steel		Count:	4		
Element Type:			Total Quantity:	4		
Environment:	Benign		Inspected	Yes <input type="checkbox"/>	No <input type="checkbox"/>	limited <input checked="" type="checkbox"/>
Protection System:	Weathering Steel and Paint					Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	each	3	1			

Comments: Graffiti was present at the west end, but no deterioration of the steel was noted. The coating appears to still be in good condition. Northwest end diaphragm bottom flange has areas of light corrosion.

Recommended Work:	Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>
			Urgent: <input type="checkbox"/>
			1 Year: <input type="checkbox"/>
			2 Year: <input type="checkbox"/>

**Element Photo:**



Description of Photo: End Diaphragms

<b>Element Data:</b>						
Element Group:	Beams/Main Longitudinal Elements		Length:	15.85		
Element Name:	Diaphragms (steel, wood, etc.)		Width:	0.15		
Location:	Intermediate		Height:	2.4		
Material:	Steel		Count:	75		
Element Type:			Total Quantity:	75		
Environment:	Benign		Inspected	Yes <input type="checkbox"/>	No <input type="checkbox"/>	limited <input checked="" type="checkbox"/>
Protection System:	Weathering Steel					Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	each	75				

Comments: **No observed defects, patina is formed and uniform.**

Recommended Work:	Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:	
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/> 1 Year: <input type="checkbox"/> 2 Year: <input type="checkbox"/>

**Element Photo:**



**Description of Photo:** Diaphragms

<b>Element Data:</b>						
Element Group:	Coating		Length:	2		
Element Name:	Structural Steel		Width:	2.2		
Location:	End of Girders		Height:	2.8		
Material:			Count:	6		
Element Type:			Total Quantity:	93.6		
Environment:	Moderate		Inspected	Yes <input type="checkbox"/>	No <input type="checkbox"/>	limited <input checked="" type="checkbox"/>
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	sq.m		45.0	30.6	18.0	

Comments: Interior coating at ends of north and south girder have failed along the bottom flange and stiffener plates exhibiting Category 3 and 4 rusting. Category 2 to 3 rusting around the drain holes in the bottom flange. Remaining coating exhibiting chalking and Category 2 rusting, typical.

Recommended Work:	Rehab: <input checked="" type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:	
Urgent: <input type="checkbox"/>	1-5 Years: <input checked="" type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/> 1 Year: <input type="checkbox"/> 2 Year: <input type="checkbox"/>
Clean debris from girder ends, recoat the girder ends.				

**Element Photo:**



**Description of Photo:** Coating

Element Data:						
Element Group:	Abutments		Length:			
Element Name:	Abutment Walls		Width:	19.5		
Location:			Height:	5.7		
Material:	Concrete		Count:	2		
Element Type:	Conventional Closed		Total Quantity:	223.5		
Environment:	Benign		Inspected	Yes <input type="checkbox"/>	No <input type="checkbox"/>	limited <input checked="" type="checkbox"/>
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	sq.m		222.0	1.5		
Comments: Light scaling, typical. Wall drains are clear. West abutment wall has been repainted, there is graffiti present. 5.7m long medium vertical crack (shown in chalk). 4.0m of light cracks.						
Recommended Work:		Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:		
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input type="checkbox"/>



Description of Photo: Abutment Wall



Element Data:						
Element Group:	Abutments		Length:			
Element Name:	Ballast Walls		Width:	19.5		
Location:			Height:	3.2		
Material:	Concrete		Count:	2		
Element Type:			Total Quantity:	126.0		
Environment:	Moderate		Inspected	Yes <input type="checkbox"/>	No <input type="checkbox"/>	limited <input checked="" type="checkbox"/>
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	sq.m		125.2	0.8		
Comments: Limited inspection, portions hidden by the diaphragms. Light scaling, typical. 3.0m medium crack at southwest area.						
Recommended Work:		Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:		
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input type="checkbox"/>

**Element Photo:**




**Description of Photo:** Ballast Wall

Element Data:						
Element Group:	Abutments		Length:	8.5		
Element Name:	Wingwalls		Width:			
Location:	All Quadrants		Height:	2.1		
Material:	Concrete		Count:	4		
Element Type:	Cast-in-Place		Total Quantity:	71.4		
Environment:	Benign		Inspected	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	sq.m		71.4			

Comments: **Light scaling, typical. No other observed defects.**

Recommended Work:	Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:	
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/> 1 Year: <input type="checkbox"/> 2 Year: <input type="checkbox"/>

**Element Photo:**



**Description of Photo:** Wingwall

Element Data:						
Element Group:	Abutments		Length:	0.5		
Element Name:	Bearings		Width:	0.6		
Location:	Bearings Seats		Height:	0.1		
Material:	Elastomeric		Count:	6		
Element Type:			Total Quantity:	6		
Environment:	Benign		Inspected	Yes <input type="checkbox"/>	No <input type="checkbox"/>	limited <input checked="" type="checkbox"/>
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	each		6			

Comments: **East end bearing pads were not accessible and were not inspected. Bearings on west end are in good condition.**

Recommended Work:	Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>
			Urgent: <input type="checkbox"/>
			1 Year: <input type="checkbox"/>
			2 Year: <input type="checkbox"/>

**Element Photo:**




**Description of Photo:** Bearings



Element Data:						
Element Group:	Retaining Walls		Length:	40.2		
Element Name:	Walls		Width:			
Location:	NW and SW Quadrants		Height:	4.0		
Material:	Concrete		Count:	1		
Element Type:	Cast-in-Place		Total Quantity:	160.8		
Environment:	Benign		Inspected	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	sq.m		159.8	1.0		
Comments: Light scaling, typical. Northwest side has cracks at 7th and 11th railing post and one 300x500mm light spall. Southwest side has medium cracks at 1st, 2nd and 7th railing post.						
Recommended Work:		Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:		
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input type="checkbox"/>

**Element Photo:**



**Description of Photo:** Retaining Wall

Element Photo:



Description of Photo: Retaining Wall

Element Photo:



Description of Photo: Retaining Wall

<b>Element Data:</b>						
Element Group:	Retaining Walls	Length:	50.0			
Element Name:	Railing System on Walls	Width:				
Location:	Under Bridge	Height:				
Material:	Steel	Count:	1			
Element Type:	Pedestrian Handrail	Total Quantity:	50.0			
Environment:	Benign	Inspected	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>	
Protection System:	Hot-Dip Galvanized					Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	m		50.0			

Comments: Pedestrian handrail along path under the west end of the bridge. Localized light corrosion and abrasion throughout. 0.5 mm narrow crack in the concrete base of a post.

Recommended Work:	Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:	
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/> 1 Year: <input type="checkbox"/> 2 Year: <input type="checkbox"/>

**Element Photo:**



**Description of Photo:** Retaining Wall Railing

Element Photo:



Description of Photo: Retaining Wall Railing

Element Photo:



Description of Photo: Retaining Wall Railing

<b>Element Data:</b>						
Element Group:	Embankments & Streams		Length:			
Element Name:	Streams and Waterways		Width:			
Location:			Height:			
Material:			Count:			
Element Type:	Waterway		Total Quantity:	1		
Environment:	Benign		Inspected	Yes <input type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	all	X				

Comments: **No observed defects.**

Recommended Work:	Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:			
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input type="checkbox"/>



**Description of Photo:** Waterway

**Element Data:**

Element Group:	Embankments & Streams		Length:		
Element Name:	Embankments		Width:		
Location:	All Quadrants		Height:		
Material:	Trees, Vegetation		Count:	4	
Element Type:			Total Quantity:	4	
Environment:	Benign		Inspected	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> limited <input type="checkbox"/>	
Protection System:				Performance Deficiencies	
Condition Data:	Units	Excellent	Good	Fair	Poor*
	each	4			

Comments: **No observed defects.**

Recommended Work:	Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>
			Urgent: <input type="checkbox"/> 1 Year: <input type="checkbox"/> 2 Year: <input type="checkbox"/>


**Element Photo:**



**Description of Photo:**      Embankments

Element Data:						
Element Group:	Embankments & Streams		Length:			
Element Name:	Slope Protection		Width:			
Location:			Height:			
Material:	Rocks and Gabion Basket		Count:	2		
Element Type:			Total Quantity:	2		
Environment:			Inspected	Yes <input type="checkbox"/>	No <input type="checkbox"/>	limited <input checked="" type="checkbox"/>
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	each	1	1			
Comments: <b>No observed defects for rock protection in front of east abutment. West side has &lt; 20% loss of material along gabion baskets beneath walkway along the waterline.</b>						
Recommended Work:		Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:		
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input type="checkbox"/>

**Element Photo:**



**Description of Photo:** Rock Protection

<b>Element Data:</b>						
Element Group:	Accessories		Length:			
Element Name:	Utilities		Width:			
Location:			Height:			
Material:			Count:	6		
Element Type:	Various		Total Quantity:	6		
Environment:			Inspected	Yes <input type="checkbox"/>	No <input type="checkbox"/>	limited <input checked="" type="checkbox"/>
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	each		6			
Comments: Limited inspection due to access. There is gas line supported along the north face of the bridge, insulated pipe (likely a watermain) under the north interior soffit, electrical and bell also appear to be supported under the north interior soffit. There are some punctures in the watermain insulation protective covering. Electrical lines are also supported along both ballast walls. The drawings indicate that there could also be hydro ducts within the sidewalks. Electrical box at northwest quadrant has a damaged latch and can be opened.						
Recommended Work:		Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:		18 - Other Maintenance
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input checked="" type="checkbox"/>	2 Year: <input type="checkbox"/>
				Replace latch and ensure electrical box can be closed and locked.		

**Element Photo:**



**Description of Photo:** Utilities



Element Photo:



Description of Photo: Utilities

Element Photo:




Description of Photo: Utilities

<b>Element Data:</b>						
Element Group:	Accessories		Length:			
Element Name:	Other		Width:			
Location:			Height:			
Material:			Count:	3		
Element Type:	Light Poles		Total Quantity:	3		
Environment:	Moderate		Inspected	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	each	3				

Comments: **No observed defects.**

Recommended Work:	Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:			
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input type="checkbox"/>



**Description of Photo:** Light Post

Element Data:						
Element Group:	Approaches		Length:	6.0		
Element Name:	Wearing Surface		Width:	15.0		
Location:	East and West		Height:	0.1		
Material:	Asphalt		Count:	2		
Element Type:			Total Quantity:	180.0		
Environment:	Severe		Inspected	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	sq.m		175.1	4.9		

Comments: Light ravelling, typical. West lane has medium wheel rutting 6.0m x 500 x 8mm. Southeast 7m of medium transverse cracks. Medium loss of bond (300mm x 300mm).

Recommended Work:	Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:	
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/> 1 Year: <input type="checkbox"/> 2 Year: <input type="checkbox"/>

**Element Photo:**



**Description of Photo:** West Approach

**Element Photo:**



**Description of Photo:** East Approach


**Element Photo:**

**Description of Photo:**

Element Data:						
Element Group:	Approaches		Length:	6.0		
Element Name:	Approach Slab		Width:	15.0		
Location:	East and West end		Height:	0.25		
Material:	Concrete		Count:	2		
Element Type:			Total Quantity:	180.0		
Environment:	Moderate		Inspected	Yes <input type="checkbox"/>	No <input type="checkbox"/>	limited <input checked="" type="checkbox"/>
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	sq.m		180.0			

Comments: **Assumed to be in good condition based on asphalt.**

Recommended Work:	Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:	
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/> 1 Year: <input type="checkbox"/> 2 Year: <input type="checkbox"/>



**Description of Photo:** Approach Slab

Element Data:						
Element Group:	Approaches		Length:	14.6 (NE) , 11.0 (SW)		
Element Name:	Barrier		Width:			
Location:	SW and NE Quadrants		Height:			
Material:	Steel Beam Guiderail		Count:	2		
Element Type:	Beam		Total Quantity:	25.6		
Environment:	Moderate		Inspected	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>
Protection System:	Galvanized					Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	8 - Pedestrian / vehicular hazard
	m	10.5	14.6		0.5	
Comments: Light coating chalking typical. Northeast end is flared with a standard end terminal hidden behind flower box with retaining wall. 3 posts have top rot. Connection to the north east barriers are substandard. Southwest rail has been replaced but has a substandard connection at bridge.						
Recommended Work:		Rehab: <input checked="" type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:		
Urgent: <input type="checkbox"/>	1-5 Years: <input checked="" type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input type="checkbox"/>
Replace substandard connections approach barrier to bridge connections						

**Element Photo:**



**Description of Photo:** Southwest Barrier

Element Photo:



Description of Photo: Southwest Barrier

Element Photo:



Description of Photo: Southwest Barrier

<b>Element Data:</b>						
Element Group:	Approaches		Length:	6.0		
Element Name:	Sidewalk/Curb		Width:	1.8		
Location:	All Quadrants		Height:			
Material:	Concrete		Count:	4		
Element Type:			Total Quantity:	43.2		
Environment:	Severe		Inspected	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	sq.m		38.9	4.3		

Comments: Light scaling, typical. 4 medium 200x200x 25mm spalls on northeast approach. 200x200x25mm medium spall, 4.5m of medium cracks and 2 - 400 x 400mm spalls on southeast approach. 7.5 of medium cracks on southwest approach. 3.0m of medium cracks and 2.0x 50mm medium spall on northwest approach. 300mm of narrow cracking at the edge of wingwalls.

Recommended Work:	Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:	
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/> 1 Year: <input type="checkbox"/> 2 Year: <input type="checkbox"/>

**Element Photo:**



**Description of Photo:** Approach Sidewalk



**Element Photo:**



**Description of Photo:** Approach Sidewalk

**Element Photo:**



**Description of Photo:** Approach Sidewalk

Repair and Rehabilitation Required:		Priority				Estimated Structural Cost
Element <sup>1</sup>	Repair and Rehabilitation Required <sup>2</sup>	6 to 10 Years	1 to 5 Years	Within 1 Year	Urgent	
Structure	Demolition					
Structure	Replacement					
OR						
Deck	Rehab. =					
Sidewalk/Curb	Rehab. = Concrete Repairs		X			\$11,000.00
Barrier	Rehab. =					
Joints	Rehab. =					
Beams	Rehab. =		X			\$60,000.00
Abutment	Rehab. =					
Pier	Rehab. =					
Other						
Estimated Rehabilitated or Replacement Structure Dimensions <sup>3</sup>						
Total Deck Length (m)		Overall Str. Width (m)		Total Structural Cost		\$71,000.00

1 - Indicate specific costs for structure replacement OR for rehabilitation under the given headings.

2 - Give a very brief description of the rehabilitation work required.

3 - Estimated structure dimensions after completion of the proposed work - if it is expected to change.

Associated Work	Comments	Estimated Associated Work Cost
Approaches	<b>Upgrade Approach Barrier to Bridge Connections</b>	<b>\$20,000.00</b>
Detours		
Traffic Control	<b>Barriers, flagging, etc.</b>	<b>\$20,000.00</b>
Utilities		
Other	<b>Engineering and contingency</b>	<b>\$80,000.00</b>
	<b>Mobilization/Demobilization, General, Insurance</b>	<b>\$50,000.00</b>
	<b>Enviromental and Access</b>	<b>\$30,000.00</b>
Total Associated Work Cost		<b>\$200,000.00</b>
Total Construction Cost		<b>\$271,000.00</b>

Justification:
Interior girder ends recommended to be cleaned and re-coated to mitigate continued corrosion. The approach guide rail connections to the bridge should be replaced with standard connections. The sidewalk concrete should be repaired to prevent tripping hazard to pedestrians and to maintain its safe use.

**Inventory Data:**

Structure Name	<input type="text" value="Waubuno Street Bridge"/>		
Main Highway #	<input type="text" value="Waubuno Street"/>	On <input checked="" type="checkbox"/> or Under <input type="checkbox"/>	Service on Structure
			<input type="checkbox"/> Navig. Water <input type="checkbox"/> Non-Navig. Water <input type="checkbox"/> Rail <input type="checkbox"/> Road <input checked="" type="checkbox"/> Ped. <input type="checkbox"/> Other
Location Description	<input type="text" value="Waubuno Street at Georgian Bay"/>	Service under:	<input type="checkbox"/> Navig. Water <input type="checkbox"/> Non-Navig. Water <input type="checkbox"/> Rail <input checked="" type="checkbox"/> Road <input type="checkbox"/> Ped. <input type="checkbox"/> Other
Owner/Custodian	<input type="text" value="Town of Parry Sound"/>		
MTO Region	<input type="text" value="Northeastern"/>	Latitude	<input n"="" type="text" value="45° 20' 34"/>
		Longitude	<input type="text" value="80° 02' 28" w"=""/>
Regional Engineer	<input type="text"/>	Heritage Designation:	<input checked="" type="checkbox"/> Not Cons. <input type="checkbox"/> Cons./Not App. <input type="checkbox"/> List/Not Desig. <input type="checkbox"/> Desig. <input type="checkbox"/> Desig./Not List <input type="checkbox"/> Desig. & List
MTO Area	<input type="text" value="52 - Huntsville"/>	Hwy Class:	Freeway <input type="checkbox"/> Arterial <input type="checkbox"/> Collector <input type="checkbox"/> Local <input checked="" type="checkbox"/>
Old County	<input type="text" value="44 - Parry Sound"/>	Posted Speed	<input type="text" value="N/A"/>
		No. of Lanes	<input type="text" value="Pathway"/>
Township	<input type="text" value="452 - McDougall"/>	AADT	<input type="text" value="N/A"/>
		% Truck	<input type="text" value="Unknown"/>
Structure Type 1	<input type="text" value="Timber Stringers"/>		
Structure Material 1	<input type="text" value="Timber"/>	Traffic Directional Bound	<input type="text" value="N-S"/>
Structure Type 2	<input type="text" value="Timber Deck"/>		
Structure Material 2	<input type="text" value="Timber"/>		
Total Deck Length	<input type="text" value="12.9"/> (m)	Inspection Frequency	<input type="text" value="2"/> (years)
Overall Str. Width	<input type="text" value="3.6"/> (m)	Inspection Year	<input type="text" value="2022"/>
Culvert Length	<input type="text"/> (m)	Inspection Duration	<input type="text" value="2"/> (hrs)
Total Deck Area	<input type="text" value="46.1"/> (sq.m)	Min. Vertical Clearance	<input type="text" value="2.96"/> (m)
Roadway Width	<input type="text" value="3.2"/> (m)	Detour Distance	<input type="text" value="N/A"/> (km)
Skew Angle	<input type="text"/> (Degree)	Fill on Structure	<input type="text" value="N/A"/> (m)
No. of Spans	<input type="text" value="3"/>	Span Lengths	<input type="text" value="3.73, 4.18, 3.53"/> (m)
For retaining wall:			
Total Wall Length	<input type="text"/> (m)	Max. Wall Height	<input type="text" value="N/A"/> (m)
Total Wall Area	<input type="text"/> (sq.m)	Ave. Wall Height	<input type="text" value="N/A"/> (m)
		Angle of Backfill	<input type="text" value="N/A"/> (Degrees)


**Historical Data**

Year Built	<input type="text" value="1981"/>	Year of superstruct. Constructed	<input type="text" value="N/A"/>
Last Reg. OSIM Inspection	<input type="text" value="2020"/>	Year of Last Minor Rehab.	<input type="text" value="N/A"/>
Last Enh. OSIM Inspection	<input type="text"/>	Year of Last Major Rehab	<input type="text" value="2009"/>
		Current Load Limit	<input type="text" value="/ /"/> (tonnes)

Work History: (Date/description)	Investigation History: (Date/description)

MTO Site Number:

Field Inspection Information:					
Date of Inspection:	June 29, 2022	Type of Inspection:	<input checked="" type="checkbox"/> Reg. OSIM	<input type="checkbox"/> Enh. OSIM	
Inspected By	Alison Friebel				
Others in Party:	Brian Wood, P.Eng.				
Eng. Access Equipment:	Camera, Tape measure, Hammer				
Special Access Equipment	None				
Weather	Sun	Temperature	24 °C		
Additional Investigations Required:		Priority			Estimated Cost
		None	Normal	Urgent	
Material Condition Survey		X			
Detailed Deck Condition Survey:		X			
Non-destructive Delamination Survey of Asphalt-Covered Deck:		X			
Concrete Substructure Condition Survey:		X			
Detailed Coating Condition Survey:		X			
Detailed Timber Investigation:		X			
Post-Tensioned Strand Investigation:		X			
Underwater Investigation		X			
Fatigue Investigation		X			
Seismic Investigation		X			
Structure Evaluation:		X			
Monitoring		X			
Deformations, Settlements and Movements:		X			
Crack Widths:		X			
RSS Horizontal movements of face:		X			
RSS Vertical movements of overall structure:		X			
RSS Local movements or deterioration of face elements:		X			
RSS Horizontal movements within overall structure:		X			
RSS Vertical movements within overall structure		X			
RSS Lateral earth pressure at the back of facing elements		X			
Investigation Notes:				<b>Total Cost</b>	<b>\$0.00</b>
Overall Structure Notes:					
Recommended Work on Structure	<input type="checkbox"/> None <input type="checkbox"/> Minor Rehab. <input checked="" type="checkbox"/> Major Rehab. <input type="checkbox"/> Replace				
Timing of Recommended Work	<input type="checkbox"/> Urgent <input checked="" type="checkbox"/> 1 to 5 years <input type="checkbox"/> 6 to 10 years				
Overall Comments:	<b>The bridge has a number of timber members with rot, with replacement of these members recommended. The key members consist of pier columns and stringers.</b>				
Date of Next inspection:	2024				
Overall Bridge Condition					
% Poor in Deck	% Poor in Beams	% Poor in Substructure	% Poor in Barrier	Bridge Condition Index (BCI or BCIp)	
2%	5%	20%	0%	BCIp 94.48	BCI 54.96
Overall Bridge Sufficiency					
Traffic	Economic	Width	Alignment	Bridge Sufficiency Index (BSI)	
2	0	0	0	52.96	

Element Data:							
Element Group:	Decks		Length:	12.8			
Element Name:	Deck Top		Width:	3.6			
Location:			Height:	0.04			
Material:	Wood		Count:	1			
Element Type:	Wood Planks		Total Quantity:	46.1			
Environment:	Benign		Inspected	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>	
Protection System:							Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*		
	sq.m		42.0	3.0	1.1		
Comments: Light weathering, typical. Light to medium checks, typical. 1 plank end at south end has raised 15mm. Severe rot in 10 planks (6 - 500 x 250mm and 4 - 300 x 250mm).							
Recommended Work:		Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:		9 - Timber Repair	
Urgent: <input type="checkbox"/>	1-5 Years: <input checked="" type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input checked="" type="checkbox"/>	2 Year: <input type="checkbox"/>	
Replace rottent planks				Fasten loose planks			
Element Photo:							
							
Description of Photo:		Deck Top					

Element Photo:




Description of Photo: Deck Top rot

Element Photo:



Description of Photo: Deck Top rot

Element Data:							
Element Group:	Sidewalk/Curb			Length:	12.8		
Element Name:	Curbs			Width:	0.2		
Location:				Height:	0.2		
Material:	Wood			Count:	2		
Element Type:				Total Quantity:	10.2		
Environment:	Benign			Inspected	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>
Protection System:							Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*		
	sq.m		6.7	1.5	2.0		
Comments: Light weathering, typical. Light to severe checks, typical. 6.0m of very severe rot through timbers.							
Recommended Work:		Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:			
Urgent: <input type="checkbox"/>	1-5 Years: <input checked="" type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input type="checkbox"/>	
Replace rotten timbers							
Element Photo:							
							
Description of Photo:		Curb					

Element Photo:




Description of Photo: Curb


Element Photo:




Description of Photo: Curb



Element Data:						
Element Group:	Barriers		Length:	12.8		
Element Name:	Railing Systems		Width:			
Location:	East and West		Height:	1.3		
Material:	Wood		Count:	2		
Element Type:	Wood Rail > 83mm Thick		Total Quantity:	25.6		
Environment:	Benign		Inspected	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	
	m		25.6			
Comments: Light weathering, typical. Lose connection at east rail 4th post.						
Recommended Work:		Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:		
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input type="checkbox"/>
Element Photo:						
						
Description of Photo:		Railing				

Element Data:							
Element Group:	Barriers			Length:	0.14		
Element Name:	Posts			Width:	0.14		
Location:				Height:	1.0		
Material:	Wood			Count:	18		
Element Type:	6x6 Timber Post			Total Quantity:	18		
Environment:	Benign			Inspected	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>
Protection System:							Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*		
	each		16	2			
Comments: Light weathering typical. 2 posts exhibit some medium splintering.							
Recommended Work:		Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:			
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input type="checkbox"/>	
Element Photo:							
							
Description of Photo:		Railing Post					

Element Data:							
Element Group:	Beams/Main Longitudinal Elements		Length:	3.6			
Element Name:	Crossties		Width:	0.20			
Location:	Under Deck		Height:	0.20			
Material:	Wood		Count:	42			
Element Type:	8x8 Timbers		Total Quantity:	60.0			
Environment:	Benign		Inspected	Yes <input type="checkbox"/>	No <input type="checkbox"/>	limited <input checked="" type="checkbox"/>	
Protection System:	Creosote						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*		
	sq.m		43.5	15.0	1.5		
Comments: Only ends of crossties were visible for inspection. Light to medium checks and splits typical. Isolated severe checks and splits.							
Recommended Work:		Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:			
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input type="checkbox"/>	
Element Photo:							
							
Description of Photo:		Crossties					


Element Photo:



Description of Photo: Cross-ties

Element Photo:

Description of Photo:

Element Data:							
Element Group:	Beams/Main Longitudinal Elements		Length:	3.73, 4.18, 3.53			
Element Name:	Stringers		Width:	0.25			
Location:			Height:	0.45			
Material:	Wood		Count:	18			
Element Type:	Rectangular Solid		Total Quantity:	288.3			
Environment:	Benign		Inspected	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>	
Protection System:	Creosote						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*		
	sq.m		244.1	28.8	15.4	1 - Load carrying capacity	
Comments: Light weathering typical. Isolated medium to severe checks and splits. Center span light splintering on the east and west exterior stringers, likely from vehicle impact. North span center stringer 2.0m of rot from abutment with severe bulging, 2nd girder from west 2.0m of rot from abutment, 6th stringer has 1.0m of rot from abutment with severe bulging and 8th stringer has 1.0m of rot from abutment. South span at pier 3rd and 7th stringer has 1.0m of rot from pier, 7th stringer has 1.0 of rot from abutment. Center span at south pier 9th stringer has 1.0m of rot from pier and 8th stringer has 1.0m of rot from north pier.							
Recommended Work:		Rehab: <input checked="" type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:			
Urgent: <input type="checkbox"/>	1-5 Years: <input checked="" type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input type="checkbox"/>	
Replace 8 rotten stringers							
Element Photo:							
							
Description of Photo:		Centre span 9th stringer					

Element Photo:




Description of Photo: North span 5th stringer rot and bulging

Element Photo:



Description of Photo: South span 7th stringer rot

Element Data:							
Element Group:	Abutments			Length:			
Element Name:	Abutment Walls/Sill			Width:	3.4		
Location:				Height:	0.69		
Material:	Wood			Count:	2		
Element Type:	Timber Wall			Total Quantity:	4.6		
Environment:	Benign			Inspected	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>
Protection System:							Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*		
	sq.m		2.8	1.2	0.6		
Comments: Light weathering, typical. Isolated severe checks and splits. North sill has severe rot in 3rd and 6th timbers from west. South sill has severe check at 4th timber from west.							
Recommended Work:		Rehab: <input checked="" type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:			
Urgent: <input type="checkbox"/>	1-5 Years: <input checked="" type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input type="checkbox"/>	
Replace poor timber sills							
Element Photo:							
							
Description of Photo:		Sill					

Element Photo:




Description of Photo: Sill Check

Element Photo:



Description of Photo: Sill Rot



Element Data:						
Element Group:	Abutments		Length:			
Element Name:	Ballast Walls		Width:	3.4		
Location:			Height:	0.70		
Material:	Wood		Count:	2		
Element Type:	Timber Wood		Total Quantity:	4.7		
Environment:	Benign		Inspected	Yes <input type="checkbox"/>	No <input type="checkbox"/>	limited <input checked="" type="checkbox"/>
Protection System:						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*	1 - Load carrying capacity
	sq.m			2.4	2.4	
Comments: Medium weathering throughout. Very severe rot at south ballast wall.						
Recommended Work:		Rehab: <input checked="" type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:		
Urgent: <input type="checkbox"/>	1-5 Years: <input checked="" type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input type="checkbox"/>
Replace south ballast wall						
Element Photo:						
						
Description of Photo:		South Ballast Wall, Rot				


Element Photo:



Description of Photo: South Ballast Wall, Rot

Element Photo:

Description of Photo:

Element Data:							
Element Group:	Piers		Length:	0.30			
Element Name:	Shafts/Columns/Pile Bents		Width:	0.30			
Location:			Height:	2.52			
Material:	Wood		Count:	12			
Element Type:	Timber Columns with Capping Beam		Total Quantity:	36.3			
Environment:	Benign		Inspected	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>	
Protection System:	Creosote						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*		
	sq.m		17.5	3.6	15.1	1 - Load carrying capacity	
Comments: Light weathering, typical. Newer timber pile cap with medium end splits. Southwest pile has been replaced. Light splintering on outer piles, likely from vehicle collisions. North pier has full height rot in column 1, 2 and 5. South pier has full height rot in 4th column and rot in top half of column 5.							
Recommended Work:		Rehab: <input checked="" type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:			
Urgent: <input type="checkbox"/>	1-5 Years: <input checked="" type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input type="checkbox"/>	
Replace 5 timber columns							
Element Photo:							
							
Description of Photo:		North Pier, Column 1					

Element Photo:



Description of Photo: North Pier, Column 2

Element Photo:



Description of Photo: North Pier, Column 5

Element Photo:





Description of Photo: North Pier

Element Photo:



Description of Photo: South Pier

Element Data:							
Element Group:	Piers		Length:	4.35			
Element Name:	Caps		Width:	0.30			
Location:			Height:	0.30			
Material:	Wood		Count:	2			
Element Type:	Timber Cap		Total Quantity:	5.6			
Environment:	Benign		Inspected	Yes <input type="checkbox"/>	No <input type="checkbox"/>	limited <input checked="" type="checkbox"/>	
Protection System:	Creosote						Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*		
	sq.m		4.0	1.6			
Comments: Light weathering, light to medium checks, typical.							
Recommended Work:		Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:			
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input type="checkbox"/>	
Element Photo:							
							
Description of Photo:		Pier Cap					

Element Data:							
Element Group:	Embankments & Streams			Length:			
Element Name:	Embankments			Width:			
Location:	All Quadrants			Height:			
Material:	Soil, Rocks and Shrubs			Count:	4		
Element Type:				Total Quantity:	4		
Environment:	Benign			Inspected	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>
Protection System:							Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*		
	each		3	1			
Comments: Medium erosion at the northwest corner and below north abutment timbers resulting in some loss of material at edges of path. Light erosion at all quadrants.							
Recommended Work:		Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:			
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input type="checkbox"/>	
Element Photo:							
							
Description of Photo:		Northwest Embankment					

Element Photo:




Description of Photo: Southwest Embankment

Element Photo:



Description of Photo: Northeast Embankment



Element Data:							
Element Group:	Embankments & Streams			Length:			
Element Name:	Slope Protection			Width:			
Location:				Height:			
Material:	Rock			Count:	2		
Element Type:	Rock Protection			Total Quantity:	2		
Environment:	Benign			Inspected	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>
Protection System:							Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*		
	each		1	1			
Comments: South end in good condition. North end has some medium loss of material with some rock protection appearing to have fallen to the base of the slope.							
Recommended Work:		Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:			
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input type="checkbox"/>	
Element Photo:							
							
Description of Photo:		South slope protection					


Element Photo:



Description of Photo: North slope protection

Element Photo:

Description of Photo:

Element Data:							
Element Group:	Accessories			Length:			
Element Name:	Signs			Width:			
Location:	North and South of Bridge			Height:			
Material:	Steel			Count:	3		
Element Type:				Total Quantity:	3		
Environment:	Benign			Inspected	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>
Protection System:							Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*		
	each		1	2			
Comments: Clearance sign is bent and worn at corners. Still in good condition. 2 no motorized vehicles signs bent and not easily visible.							
Recommended Work:		Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:		18 - Other Maintenance	
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input checked="" type="checkbox"/>	
				Relocate no motorized vehicles to be easily visible.			
Element Photo:							
							
Description of Photo:		No motorized vehicles sign					


Element Photo:




Description of Photo: Clearance sign

Element Photo:

Description of Photo:

Element Data:							
Element Group:	Accessories			Length:			
Element Name:	Utilities			Width:			
Location:	North and South of Bridge			Height:			
Material:				Count:	1		
Element Type:	Cable			Total Quantity:	1		
Environment:	Benign			Inspected	Yes <input type="checkbox"/>	No <input type="checkbox"/>	limited <input checked="" type="checkbox"/>
Protection System:							Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*		
	each			1			
Comments: Limited inspection due to cable height. Does not appear to be properly supported.							
Recommended Work:		Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:			
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input type="checkbox"/>	
Element Photo:							
							
Description of Photo:		Utility					

Element Data:							
Element Group:	Approaches			Length:	6.0		
Element Name:	Wearing Surface			Width:	3.6		
Location:	North and South end of Bridge			Height:			
Material:	Gravel			Count:	2		
Element Type:				Total Quantity:	43.2		
Environment:	Benign			Inspected	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>	limited <input type="checkbox"/>
Protection System:							Performance Deficiencies
Condition Data:	Units	Excellent	Good	Fair	Poor*		
	sq.m		43.2				
Comments: Light rutting. No other observed defects.							
Recommended Work:		Rehab: <input type="checkbox"/>	Replace: <input type="checkbox"/>	Maintenance Needs:			
Urgent: <input type="checkbox"/>	1-5 Years: <input type="checkbox"/>	6-10 Years: <input type="checkbox"/>	None: <input checked="" type="checkbox"/>	Urgent: <input type="checkbox"/>	1 Year: <input type="checkbox"/>	2 Year: <input type="checkbox"/>	
Element Photo:							
							
Description of Photo:		Approach looking south					

**Element Photo:**



**Description of Photo:** Approach looking north

**Element Photo:**

**Description of Photo:**

Repair and Rehabilitation Required:		Priority				Estimated Structural Cost
Element <sup>1</sup>	Repair and Rehabilitation Required <sup>2</sup>	6 to 10 Years	1 to 5 Years	Within 1 Year	Urgent	
Structure	Demolition					
Structure	Replacement					
OR						
Deck	Rehab. = Replace Rotten Planks		X			\$2,000.00
Sidewalk/Curb	Rehab. = Replace Rotten Curbs		X			\$5,000.00
Barrier	Rehab. =					
Joints	Rehab. =					
Beams	Rehab. = Replace Rotten Stringers		X			\$50,000.00
Abutment	Rehab. = Replace Ballast Wall		X			\$12,000.00
Pier	Rehab. = Replace Rotten Columns		X			\$11,000.00
Other						
Estimated Rehabilitated or Replacement Structure Dimensions <sup>3</sup>						
Total Deck Length (m)		Overall Str. Width (m)		Total Structural Cost		\$80,000.00

- 1 - Indicate specific costs for structure replacement OR for rehabilitation under the given headings.  
2 - Give a very brief description of the rehabilitation work required.  
3 - Estimated structure dimensions after completion of the proposed work - if it is expected to change.

Associated Work	Comments	Estimated Associated Work Cost
Approaches		
Detours		
Traffic Control		\$5,000.00
Utilities		
Other	<b>Engineering and Contingency</b>	\$15,000.00
	<b>General, Mobilization/Demobilization, Access, General</b>	\$40,000.00
Total Associated Work Cost		\$60,000.00
Total Construction Cost		\$140,000.00

**Justification:**

The deteriorated timber deck, curbs, ballast wall, stringers and columns should be replaced as the rot will continue to progress. Signs of bulging and deterioration are already evident for severe rot.